



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
T K MOTOR WORKSHOP BLK 1 KAKI BUKIT AVE 6 #02-56 SINGAPORE 417883 ON BEHALF OF KURUBALAN S/O MANICKAM			Ref: CS/TP21009227/Aqcn2 Date: 21/02/2022 Code: TP179	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	Veh. Inspected	SGJ 5116G	
	Policy No.	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	0.00	
	Assign From	Assign Date	31/08/2021	
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN SUNNY	c.c	1597
	Engine No.	HIDDEN	Year of Reg.	2006
	Chassis No.	JN1CFAN16Z0101683	Colour	GOLD
	Odometer	109077 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/65 R15	DUNLOP	6 mm
	L/H Front Tyre	185/65 R15	DUNLOP	6 mm
	R/H Rear Tyre	185/65 R15	DUNLOP	6 mm
	L/H Rear Tyre	185/65 R15	DUNLOP	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	19/08/2021	Inspection Date	31/08/2021
	Survey held at	T K MOTOR WORKSHOP BLK 1 KAKI BUKIT AVE 6 #02-56 SINGAPORE 417883		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	