

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



AUTOMOBILE INSPECTION REPORT



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC21009231/Vtcn2						
NIOC	INCOME INSUR	ANCE CO-OPERATIVE LTD	Rei.	NS/INC21009231/V	(tcn2	
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556				09-09-2021 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	GBH 4681S		nspected	SHA 3553B	
	Policy No.		Cover	age (\$)	0.00	
	Claim No.	MT/1142594-002	Exces	s (\$)	0.00	
	Assign From		Assign	n Date	30/08/2021	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI IONIQ	c.c		1580	
	Engine No.	HIDDEN	Year o	f Reg.	2020	
	Chassis No.	KMHC851CVLU188876	Colou	r	BLUE	
	Odometer	94260	Steerii	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	WEST	LAKE	5 mm	
	L/H Front Tyre	195/65 R15	WEST	LAKE	5 mm	
	R/H Rear Tyre	195/65 R15	WEST	LAKE	5 mm	
	L/H Rear Tyre	195/65 R15	WEST	LAKE	5 mm	
4.						
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	27/08/2021	Inspec	tion Date	30/08/2021	
	Survey held at	at COMFORTDELGRO ENGINEERING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					