

(08/11/13) WEL
ASS. REC. BY: mm

REF:

CS/CTI 21009238/R19c

0634

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMS 6377U

at Workshop m/s Cycle & Carriage

of 209, Pansong Road

Insured:

CTI

Policy No.

Claims No.

SNM21D204905/C02

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

81K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

12

days

Res.:

Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

Repair Int - 44K

03/09/21@3.45pm revised to Irene Tay via Merimen.

12/11/21@5.03pm Rasul finalised with Ai Ting final fig \$13466, 12 days.(Red \$1688, 11%)

Veh No:

SMS 6377U

Yr Regn:

2020 / MAR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

KIA CERATO 1.6 P EX

c.c 1591

Colour

RED

A/C: Insured / Std / NI / NA

Sp.Reading

20386

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KNAF3416ML5069379

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NII / SRim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kumho

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

27/08/21

D.O.I.

02/09/21

Survey held at

Cycle

Des. of Damages: Frt / Rear / 018 / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1) 22/11 Typist

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 12

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) _ \$ + RS _ \$I

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format : MER-TP

Lump Sum / I.B.I.: (\$ 13466)

TOTAL



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
TAN CHOON LENG ALEX	Cust No/Name	LCV12163/TAN CHOON LENG ALEX
15 BEDOK RESERVOIR VIEW	Reg No/Reg Date	SMS6377U / 06/03/202
#01-03	Date In/Mileage	27/08/2021/ 0
SINGAPORE 478933	Chassis No	KNAF3416ML5069379
Contact No	Engine No	G4FGKH755239
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LCV12163	CRDVCH	01/09/2021/ 09:46	QUK	282 / Kevin Leong	38568		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							3840.00
REPLACE FRT RH DOOR, REAR RH DOOR, RH WING MIRROR ASSY, @ 640 x 5							3200
REAR RH FENDER & AFFECTED AREA							2360.00
E PNT98000							1850
PAINT WORK ON FRT RH DOOR, REAR RH DOOR, REAR RH FENDER, - @ 550 x 3 = 1650							160
RH WING MIRROR COVER & FRT RH DOOR HANDLE 200							160
E PNT88000							150
TO TRANSFER FRT RH DOOR ATTACHMENTS TO NEW PANEL							150
E PNT88000							150
TO TRANSFER REAR RH DOOR ATTACHMENTS TO NEW PANEL							150
E PNT88000							300.00
REMOVE & INSTALL REAR SEAT FOR FACILITATE REPAIR							80.00
E PNT88000							150
REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR							120
E PNT88000							120.00
REMOVE & INSTALL REAR WINDSCREEN GLASS FOR FACILITATE REPAIR							280.00
M SUNDRY							180.00
APPLY WINDSCREEN SEALANT							50.00
M SUNDRY							480.00
TO APPLY SEALANT ON AFFECTED AREA							30
M SUNDRY							50.00
PERFORM RUST PREVENTION							
A 54900099							
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							
A 10028901							
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							
B WHEELALIGNMENT							
To Conduct Computerize Full Wheel Alignment							
M SUNDRY							
TO TRANSFER REAR RH RIM INCLUDING BALANCING							
M SUNDRY							
TO SUPPLY REAR RH SPORT RIM sd							
M SUNDRY							

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
TAN CHOON LENG ALEX	Cust No/Name	LCV12163/TAN CHOON LENG ALEX
15 BEDOK RESERVOIR VIEW	Reg No/Reg Date	SMS6377U / 06/03/202
#01-03	Date In/Mileage	27/08/2021/ 0
SINGAPORE 478933	Chassis No	KNAF3416ML5069379
Contact No	Engine No	G4FGKH755239
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV12163	CRDVCH	01/09/2021/ 09:46	QUK	282 / Kevin Leong	38568
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
SUNDRIES					
M MIRROR ASSY-OUTSIDE RR VIEW, RH <i>cm</i>		1.00	559.00	00.00	559.00
M PANEL ASSY-FRONT DOOR, RH <i>buc</i>		1.00	1277.00	00.00	1277.00
M PANEL ASSY-REAR DOOR, RH <i>buc</i>		1.00	1377.00	00.00	1377.00
M PANEL ASSY-QUARTER OUTER, RH <i>buc</i>		1.00	1349.00	00.00	1349.00
M MOULDING ASSY-FRT DR FRAME, RH <i>re</i>		1.00	37.00	00.00	37.00
M W/STRIP ASSY-FR DR BELT O/S RH ?		1.00	64.00	00.00	64.00
M W/STRIP ASSY-FR DR SIDE RH ?		1.00	102.00	00.00	102.00
M HANDLE ASSY-DOOR OUTSIDE, RH <i>ds</i>		1.00	164.00	00.00	164.00
M PAD-FR DR O/S HDL HINGE, RH <i>re</i>		1.00	5.00	00.00	5.00
M PAD-FR DR O/S HDL COVER, RH <i>ds</i>		1.00	5.00	00.00	5.00
M COVER-FR DR O/S HDL RH <i>ds</i>		1.00	14.00	00.00	14.00
M BASE ASSY-FR DR O/S HANDLE RH ?		1.00	52.00	00.00	52.00
M LATCH ASSY-FRONT DOOR, RH ?		1.00	400.00	00.00	400.00
M MOULDING ASSY-RR DR FRAME, RH <i>re</i>		1.00	44.00	00.00	44.00
M W/STRIP ASSY-RR DR BELT O/S RH ?		1.00	60.00	00.00	60.00
M W/STRIP ASSY-RR DR SIDE RH ?		1.00	102.00	00.00	102.00
M BLACK TAPE-FR DR RR, RH <i>re</i>		1.00	13.00	00.00	13.00
M BLACK TAPE-RR DR FR, RH <i>re</i>		1.00	13.00	00.00	13.00
M BLACK TAPE-RR DR FRAME RR OTR, <i>re</i>		1.00	8.00	00.00	8.00
M FILM-ANTI CHIPPG RH <i>re</i>		1.00	27.00	00.00	27.00

SURVEYOR NAME: *Rasul - Hp 90010068*SURVEYOR SIGNATURE: *[Signature]*DATE: *02/09/21 @ 1150*REMARKS: *12 days**Reg before paint*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

Nett 14,492.00
7% GST on 14492.00 1014.44

Total Payable 15,506.44

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	27/08/2021 13:24 (SGT)
Date of Accident	27/08/2021 09:23 (SGT)
Exact Location of Accident	Temasek Poly East G, Singapore
Additional Location Information	TEMASEK POLYTECHNIC EAST GATE, TAMPINES AVE 1
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMS6377U
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	ALEX TAN CHOON LENG
NRIC No	SXXXX063H
Email Address	AYJK35@GMAIL.COM
Mobile Phone No	(Phone) +65-90621989
Alternative Phone No	+65-93859314

VEHICLE PARTICULARS

Manufacturer	Kia
Model	Cerato
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1591

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	2070033088
Cover Note Number	-

DRIVER

Name of Driver	JAENYNE TAN LING XIN
NRIC No	TXXXX218G



Date Of Birth	08/12/2000
Occupation	Indoor
Date Of Driving Pass	04/03/2019
Driving experience	2 YEARS AND 5 MONTHS
Gender	Female
Mobile Number	(Phone) +65-93859314
Alt. Phone Number	-
Email Address	JAENYNE@GMAIL.COM
Address	BLK 15 BEDOK RESERVOIR VIEW #01-03
Address complement	-
Postcode	478933
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Child
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	KAELYNE TAN JING WEI
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YQ4211X
Vehicle Manufacturer	Mitsubishi
Vehicle Model	Canter
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle

Name of Driver
Contact Number

MUTHAIAH PACKIARAJ
(Phone) +65-90665309

Address
Address complement

-
-
-

Postcode

Insurance Company Name

China Taiping Insurance (Singapore) Pte. Ltd.

Nature Of Damage

-
-
-

Details of property damaged in accident

No. Of Passenger (Including Driver)

INSURED : SMC 9617 S

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :


(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.


(collectively the "**Purposes**")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time




Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

I was driving ~~along~~ to send my sister (kaelyne Tan) to school (Temasek Poly) main entrance at 9:20 am. I was driving on the extreme left lane when suddenly the lorry swerved to the left and damaged the entire right side of my car.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	063H
Vehicle No.:	SMS6377U
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Sep 2021
Vehicle Make:	KIA
Vehicle Model:	CERATO 1.6(A) EX
Primary Colour:	Red
Manufacturing Year:	2019
Engine No.:	G4FGKH755239
Chassis No.:	KNAF3416ML5069379
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$14,866.00
Original Registration Date:	06 Mar 2020
First Registration Date:	06 Mar 2020
Transfer Count:	0
Actual ARF Paid:	\$14,866.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Mar 2030
PARF Rebate Amount:	\$11,149.00
COE Expiry Date:	05 Mar 2030
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$30,010.00
COE Rebate Amount:	\$25,524.00
Total Rebate Amount:	\$36,673.00

The information contained herein is correct as at 03 Sep 2021

OK

Kia Cerato 1.6A EX

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price

\$81,777

Depreciation ?

\$8,720 /yr

[View models with similar depre](#)

Reg Date

11-Mar-2020

(8yrs 6mths 7days COE left)

Mileage

25,907 km (17.5k /yr)

Manufactured ?

2019

Road Tax ?

\$738 /yr

Transmission

Auto

Dereg Value ?

\$39,317 as of today (change)

OMV ?

\$14,933

COE ?

\$32,999

ARF ?

\$14,933

Engine Cap

1,591 cc

Power

93.8 kW (125 bhp)

Curb Weight ?

1,287 kg

No. of Owners ?

1

Type of Vehicle

Mid-Sized Sedan

Features

1.6L Engine With Dual-CVT Technology, 125Bhp/155Nm, 6-Speed AT Transmission, Daytime Running Lights, Cruise Control. [View specs of the Kia Cerato \(2018-2021\)](#)