

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

Our Ref

: 305485451

Date

: 02-09-21

Time of Fax

:

Via Fax

: EMAIL

Your Insured

: SMU 915X

Date of Acc

: 01-09-21

Attn: Motor Claims Department

ALG

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH

882X

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

◆ Lim Kwok Eng	Tel: 6214 8355 or HP: 9824 0811
◆ Jumani Bin Masudin	Tel: 6214 8315 or HP: 9635 5305
◆ Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546
◆ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006

} **jumanibm@cdge.com.sg**
Fax no. 6546 8156

→ If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

For Vice President
Taxi Accident Repair


Team: ARC Repair TP(CLSO)1 JOB CARD Sales Order: 4114977 JC NO.:305485451

OWNER	REGN NO.: SH 8832X	MILEAGE
IS OWNER NO. 7010045	MAKE: TOYOTA	FUEL E.....1/2.....F
RESS 383 SIN MING DRIVE	MODEL PRIUS HYBRID(G4)02	DATE/TIME IN 09.2021 11:40
Singapore SINGAPORE 575717	YR OF MANU. 30.12.2016	TARGET DATE
(R) 65508755 (O)	CHASSIS CODE JTDKB3FU203538941	COMPLETION DATE/TIME:
(P)		
COUNT CARD NO.		

JOB DESCRIPTION

Accident Date: 01.09.2021
NATURE: 3P031.09.2021

LABOR CODE DESCRIPTION



KED & PASSED OUT BY: _____

SERVICE ADVISOR _____ CUSTOMER'S SIGNATURE _____

edgement Slip

Exit Pass

Vehicle No.: **SH 8832X**

Signature/Date _____ Name of Service Advisor _____ Date _____

turned to Service Reception upon collection

To be kept by Security Guard


INSURER ENQUIRY

**Find
insurer**

Vehicle reg. no.

SMU915X

Date of Accident

01/09/2021 

Reset

% **RESULT & RECEIPT**

TP Insurer Enquiry

Insurance **AIG Asia Pacific Insurance Pte....**

Period of Insurance **29/07/2020 - 28/07/2022**

Requested By **Por Moy Juan (COMFORTDELG...**

Requested Date **02/09/2021 13:50**

Payment details

Request Amount: **S\$1.87**

GST Amount: **S\$0.13**

Total Amount Due (GST Inclusive): **S\$2**

General Insurance Association

Records Management Centre

GST Registration No: **M400017735**

Sri 8832X

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305485451
REGN NO : SH 8832X
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4)
DATE OF REGN : 30.12.2016
DATE/TIME IN : 02.09.2021 11:40
ACCIDENT DATE : 01.09.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-2282-G	COVER REAR BUMPER%	1	499.90	25.00	374.92
0002 04-01-0302-2267-G	BUMPER PIECE	1	2.20	25.00	1.65

SUB-TOTAL : 376.57

JOB NATURE

0000 PB	PANEL BEATING	400.00
0001 SP	SPRAYPAINT CHARGE	300.00

SUB-TOTAL : 700.00

TOTAL : 1,076.57

AUTHORISED : YES / NO

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :