Our Job Ref No 305485451					ENGINEERING		
Date 04/09/21					ComfortDe/Gro Engineering Pte Ltd 59 Loyang Drive Singapone 508989		
FINALIZATION FORM							
To	:	LKK			Fex		
Attn	THEVAN						
		: SH 8	3832X		DO	A: 01/09/21	
The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-							
1.	The	epair job shall b	ill to:	AIG		SMU815X	
2.	The finalized amount shall be:				t#-	#	
	(a) Spare Parts after List discount						
	(b) Labour Charges					\$600.00	
		Total for Part-	By-Part Repair Co	st		\$600.00	
	(c.)	Lumpsum Rep Total for Lumpsu Final Lumpsu	air (if applicable) sum repair cost after m Repair cost	Less: <u>20%</u>	<u>)</u>		
<ul><li>3.</li><li>4.</li></ul>	Estimated normal period for repairs: working days  We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days						
5.	Thank you for your assistance.				We confirm the estimates and finalized amount		
	Signature :			_ Na	Signature: Name: Date:    O 9 7		
For O	fficial	Use Only					
	Item		Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks	
Rental Rate P/Day				YES			
2. Loss of Income Paid				N			
3. Survey Fees				-			
<ol> <li>LTA Search Fee</li> <li>Medical Fees (on behalf</li> </ol>			7.49 / 2.00	-			
of c	driver, i	f applicable)					
6 Overrun							
Remarks:							

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 04.09.2021 Time: 08:53:06

Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

REGN NO MILEAGE

JOB NO

: 305485451 : SH 8832X

: 0000000000

MAKE

: TOYOTA

MODEL

: PRIUS HYBRID(G4)

DATE OF REGN

: 30.12.2016

DATE/TIME IN : 02.09.2021 11:40

ACCIDENT DATE : 01.09.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

SUB-TOTAL: 0.00

JOB NATURE

0000 PB

PANEL BEATING

350.00

0001 SP

SPRAYPAINT CHARGE

250.00

SUB-TOTAL : 600.00

TOTAL : 600.00

MVA NAME & SIGNATURE

DATE:

AUTHORISED: YES / NO

SURVEYOR NAME & SIGNATURE

DATE:

## COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 02.09.2021

Time: 14:29:01

Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO REGN NO : 305485451 : SH 8832X

MILEAGE

: 0000000000

MAKE

: TOYOTA

MODEL

: PRIUS HYBRID(G4)

DATE OF REGN

: 30.12.2016

DATE/TIME IN ACCIDENT DATE : 02.09.2021 11:40 : 01.09.2021

JOB / PARTS DESCRIPTION

OTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

front

0001 04-01-0302-2282-G COVER REAR BUMPER% 1 499.90 25.00 374.92 XY

0002 04-01-0302-2267-G BUMPER PIECE

1 2.20 25.00 1.65 X SUC

SUB-TOTAL: 376.57

JOB NATURE

0000 PB

PANEL BEATING

400.00 350

0001 SP

SPRAYPAINT CHARGE

300.00 250

SUB-TOTAL: 700.00

MVA NAME & SIGNATURE

TOTAL: 1,076.57

AUTHORISED: YES / NO

SURVEYOR NAME & SIGNATURE

DATE:

Thuan With 81235769 theran elkh auto-bu Labour only zdays wp 2/9/2/ 14/6/5

L/s after repair photos

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: