

ASS. REC. BY: TGLM

REF:

CS/CT121009281/BTC

Denise

## ASSIGNMENT

From:

Date: 6/9/2021

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SNA 96244

at Workshop m/s MS Cars

of 8 Kaki Bt Ave 4 Premier # 01-07

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

64,000/-

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SNA 96244

Yr Regn: 16/11/2016

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 116d 5Dr

C.C. 1496

Colour:

Grey

AC: Insured / Std / NI / NA

Sp. Reading:

66522

T/Radio: Insured / Std / NI / NA

Eng/No:

36569750B37D15A

C/No:

WBAIV72010V725456

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 225/45/18 225/40R18

R: 225/45/18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

28/8/2021

D.O.I.

6/9/2021

Survey held at

MS Cars

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range 6,000/- - 7,000/-

Recommended COR is LS \$6350.00/- TGLM 18/9/2021

\* Invoice must be provided before COR offered can be amended.

RED:13707.45;68%

MV 64,000/-

PV 36,483/-

NV 27,517/-

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Rep. Format:

Lump Sum / L.B.I. /

Days Of Repair: 5

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL



SJE :

Date of Survey :

Contacts :

Vehicle Nos : SNA 9642U

Model : BMW 116D DSR LED

Year :

**\* AGREED Cost Of Repair and Repair Day/s with SJE \***

Amount:

Working Day:

2016

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear door R/H DD✓	1	\$ 1,650.95	\$ 1380.20 1,650.95
2	Rear door hinge R/H BT✓	2	\$ 115.00 227.80	\$ 230.00 455.60
3	Rear door board R/H BR✓	1	\$ 437.50	\$ ✓ 437.50
4	Rear glass R/H BR✓	2	\$ 258.30	\$ ✓ 258.30
5	Rear door outer moulding R/H BT✓	1	\$ 153.30	\$ ✓ 153.30
6	Rear pillar R/H NDX	1	\$ 883.50	\$ 883.00
7	Rear bumper CUTV	1	\$ 1,424.45	\$ 1220.30 1,424.45
8	Rear bumper reinforcement NDX	1	\$ 878.55	\$ 878.55
9	Rear bumper side bracker R/H NECV	1	\$ 151.85	\$ ✓ 151.85
10	Rear clomh NDX	2	\$ 113.50	\$ 227.00
11	Rear door handle DDV	1	\$ 166.10	\$ ✓ 166.10
12	Rear fender R/H DDV	1	\$ 786.20	\$ ✓ 786.20
13	Rear fender support bracket R/H NNX	1	\$ 161.35	\$ 161.35
14	Rear fender cowling R/H NNX	1	\$ 216.60	\$ 216.60
15	Rocker panel RH CUTV	1	\$ 407.25	\$ ✓ 407.25
16	Rear knuckle arm RH DDV	1	\$ 594.10	\$ ✓ 594.10
17	Rear shock absorber RH BTV	1	\$ 610.90	\$ 386.70 610.90
18	Rear steering rack and pinion NSX	1	\$ 3,286.25	\$ 3,286.25
19	Rear regulator BT✓	1	\$ 329.40	\$ 253.95 329.40
20	Rear regulator motor SCV	1	\$ 583.80	\$ 323.80 583.80
21	Tail lamp R/H NDX	1	\$ 840.35	\$ 840.35
22	Tail lamp bracker R/H NDX	1	\$ 112.65	\$ 112.65
			Parts Sub Total :	\$ 14,615.45
			PARTS TOTAL :	\$ 14,615.45

@ 50%

 6749.55  
 337.49  
 6412.07

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Rear bumper clips NECV	10	\$ 5.00	\$ 30.00 50.00
2	Rear fender cowling clips NNX	8	\$ 5.00	\$ 40.00
3	Wheel rim front R/H To provide invoice BR✓	1	\$ 1,526.00	\$ * * 1,526.00
4	Front wheel R/H RED: NDX	1	\$ 426.00	\$ 426.00
SPECIAL NETT TOTAL :				\$ 30.00 2,042.00

Nos.	LABOUR	S\$
1	Labour accident affected area	\$ 800.00 1,600.00
2	Spray painting	\$ 600.00 1,500.00
3	Check alignment	\$ 60.00 200.00
4	Realign rear wheel	\$ 40.00 100.00
LABOUR TOTAL :		\$ 1500.00 3,400.00

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Survey Resurvey  
 6/9/2021 8/9/2021  
 Titim Wu Titim Wu  
 1340 hrs 1630 hrs  
 Lump sum repair  
 Repair days

LS 6350.00

\* Invoice must be provided  
 before COR offered can be amended.

PARTS TOTAL : \$ 6412.07 14,615.45  
 SPECIAL NETT TOTAL : \$ 30.00 2,042.00  
 LABOUR TOTAL : \$ 1500.00 3,400.00  
 TOTAL : \$ 7942.07 20,057.45  
 Deduct 20% : \$ 1588.41 4,011.49  
 GRAND TOTAL : \$ 6353.66 15,083.40



# MotorMed Pte Ltd

8 Kaki Bukit Ave 4 #02-14/44

Premier @ Kaki Bukit

Singapore 415875

Phone Number: 69777077

Fax Number: 69777080

Customer:			Date: 30/8/2021 éú□		
Company: 01-07			VIN SNA9624U		
License NO:			Technician:		
Odometer:			Order NO:		

VEHICLE ALIGNMENT REPORT						
BMW, 1 SERIES (F20) RWD Standard Suspension except M135i, 11-18 (Customized)						
Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	---	---	---	---
		Right	---	---	---	---
	Camber	Left	-0°06'	-0°45'	0°05'	-0°06' ✓
		Right	-0°12'	-0°45'	0°05'	-0°12' ✓
	Toe	Left	-1°01'	0°05'	0°09'	-1°01' X
		Right	1°28'	0°05'	0°09'	1°28' X
Total		0°27'	0°10'	0°18'	0°27' X	
Rear	Camber	Left	-1°06'	-1°35'	-1°25'	-1°06' X
		Right	-1°36'	-1°35'	-1°25'	-1°36' X
	Toe	Left	0°09'	0°07'	0°11'	0°09' X
		Right	-2°07'	0°07'	0°11'	-2°07' X
		Total	-1°58'	0°14'	0°22'	-1°58' X
	Thrust Angle		-1°08'	0°12'		-1°08' X
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left	---	---	---	---	---
	Right	---	---	---	---	---
Included Angle	Left	---	---	---	---	---
	Right	---	---	---	---	---
Toe Out On Turns	Left	---	1°33'	1°33'	---	---
	Right	---	1°33'	1°33'	---	---
Max Turn Inside	Left	---	40°24'	40°24'	---	---
	Right	---	40°24'	40°24'	---	---
Toe Curve Change	Left	---	---	---	---	---
	Right	---	---	---	---	---
Setback	Front	-0.0"	---	---	---	-0.0"
	Rear	-0.1"	---	---	---	-0.1"
Track Width Diff.		-0.8"				-0.8"
		0.1"				0.1"
Front Ride Height	Left	---	23.5"	24.3"	---	---
	Right	---	23.5"	24.3"	---	---
Rear Ride Height	Left	---	23.3"	24.1"	---	---
	Right	---	23.3"	24.1"	---	---
Frame Angle						---



# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission ..... 30/08/2021 12:46 (SGT)  
Date of Accident ..... 28/08/2021 09:55 (SGT)  
Exact Location of Accident ..... Singapore  
Additional Location Information ..... PIE CHANGI AFTER BKT BATOK  
Country/State of Loss ..... Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SNA9624U

### INSURED/POLICYHOLDER

Is company? ..... No  
Name Of Registered Owner ..... MUHAMMAD DIRSHEE BIN ELIAS  
NRIC No ..... SXXXX739H  
Email Address ..... DIRXZ@LIVE.COM  
Mobile Phone No ..... (Phone) +65-91801585  
Alternative Phone No ..... (Home) +65-91801585

### VEHICLE PARTICULARS

Manufacturer ..... BMW  
Model ..... 116d  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... Private use  
Are you claiming under your own insurance policy for repair to your vehicle? ..... No - Claiming third party  
Vehicle Category ..... Private car  
Transmission ..... Auto  
CC ..... 1496

### INSURANCE COMPANY

Name of Insurance Company ..... NTUC Income Insurance Co-operative Ltd  
Type of Coverage ..... Comprehensive  
Fleet Policy ..... No  
Policy Number ..... 5123477613  
Cover Note Number ..... -

### DRIVER

Name of Driver ..... MUHAMMAD DIRSHEE BIN ELIAS  
NRIC No ..... SXXXX739H



Date Of Birth .....	21/01/1995
Occupation .....	Indoor
Date Of Driving Pass .....	11/02/2019
Driving experience .....	2 YEARS AND 6 MONTHS
Gender .....	Male
Mobile Number .....	(Phone) +65-91801585
Alt. Phone Number .....	(Home) +65-91801585
Email Address .....	DIRXZ@LIVE.COM
Address .....	BLK 853 YISHUN RING ROAD #05-3527
Address complement .....	-
Postcode .....	760853
Is the driver the policyholder? .....	Yes
If No, Relationship of the Driver with the Insured .....	-
Does Driver Own Other Vehicles? .....	No
Vehicle Registration Number of Other Vehicle Owned by Driver .....	-
Insurance Company of Other Vehicle Owned by Driver .....	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident .....	Collision - Change/cross lane
Weather Conditions .....	Clear
Road Surface .....	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? .....	No
Number of vehicles involved in the accident .....	2
Was anybody injured in the Accident? .....	No
Was any injured conveyed to hospital by ambulance? .....	-
Was any other vehicle or property damaged? .....	Yes
Number of Passengers (Including Driver) .....	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? .....	No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? .....	No
Was notice of intended Prosecution given? .....	No
If yes, against whom? .....	-

#### CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHED

#### ATTACHMENT(S)

Are accident photos available for attachment? .....	Yes
Was there any video captured by Car Camera? .....	No
Was there any audio recorded? .....	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number .....	XD8106X
Vehicle Manufacturer .....	-
Vehicle Model .....	-
Vehicle Variant .....	-
Vehicle Colour .....	-
Vehicle Category .....	Commercial vehicle
Name of Driver .....	-
Contact Number .....	-
Address .....	-
Address complement .....	-




Postcode ..... -  
Insurance Company Name ..... -  
Nature Of Damage ..... -  
Details of property damaged in accident ..... -  
No. Of Passenger (Including Driver) ..... -





**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that:
  - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

  
Policyholder's Signature Date  
& Time:

Driver's Signature  
(If driver is not the policyholder) Date  
& Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**SKETCH PLAN**





**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

At mentioned Date and Time, I was  
 driving PIE Changi After Bukit Batok, suddenly  
 feel a strong impact from my right portion  
 and my vehicle spin and facing opposite  
 direction.

A: SNA 9642 U  
 B: XD 8106X

**DECLARATION**

I/We declare the foregoing particulars are true in every respect.

 Policyholder's Signature Date & Time	Driver's Signature (If driver is not the policyholder) Date & Time	 Reporting Centre Personnel's Signature Name: NRIC/FIN NO.:
--	--	---



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	739H
<b>Vehicle Details</b>	
Vehicle No.:	SNA9624U
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Sep 2021
Vehicle Make:	B.M.W.
Vehicle Model:	116D 5DR HATCH DSC LED
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	36569750B37D15A
Chassis No.:	WBA1V72010V725456
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$25,133.00
Original Registration Date:	16 Nov 2016
First Registration Date:	16 Nov 2016
Transfer Count:	1
Actual ARF Paid:	\$12,187.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Nov 2026
PARF Rebate Amount:	\$9,140.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	15 Nov 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,668.00
COE Rebate Amount:	\$27,343.00
<b>Total Rebate Amount:</b>	<b>\$36,483.00</b>

The information contained herein is correct as at 06 Sep 2021

OK

MV 64,000/2

PV 36,483/2

NV 27,517/2

Trum Win  
6/9/2021



## Cheap Car Insurance Renewal

Is your car insurance expiring soon?

Receive best quotations from multiple insurers in as little as 2 hours.

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$68 until it's SOLD!**

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Dec 2020 Toyota Supra GR 2.0 Special Offer \$232,800!



In House Finance Available!  
Super Low Mileage! Agent  
Warranty & Serviced!  
Speedo Motoring StarAd

**Lake View**

view our cars

as guaranteed  
in Japanese cars  
approval  
are negotiable

Browse by Category

« Back ( 1 2 ) Next »

39 vehicles



BMW 116d

Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	<b>BMW 116d</b>	Any	Any	<b>2016</b>	Any	Any	Any	All
	<b>BMW 1 Series 116d</b>	<b>\$71,800</b>	<b>\$12,550 /yr</b>	<b>13-Dec-2016</b>	<b>1,496 cc</b>	<b>77,315 km</b>	<b>Hatchback</b>	<b>Available</b>
<b>Fuel Type:</b> Diesel (Euro 5 Engine and Above) Consignment Unit, Very Well Maintained By Owner. Contact Us To Arrange For A Viewing! Posted: 20-Aug-2021 Tags: 2016 BMW 116d, BMW 116d, BMW, 116d								
	<b>BMW 1 Series 116d</b>	<b>\$68,800</b>	<b>\$12,060 /yr</b>	<b>30-Nov-2016</b>	<b>1,496 cc</b>	<b>72,400 km</b>	<b>Hatchback</b>	<b>Available</b>
<b>Fuel Type:</b> Diesel (Euro 5 Engine and Above) F20 LCI Bodykit (M2 Look), Dual Exhaust Tip, Carbon Fiber Side Mirror, Carbon Fiber Boot Lip, Front Grille Carbon Fiber. Fresh Coat Of Paint. Warranty Optional. Come On Down And View This Little Beast With A Low Depreciation. Posted: 06-Sep-2021 Tags: 2016 BMW 116d, BMW 116d, BMW, 116d								
	<b>BMW 1 Series 116d</b>	<b>\$68,888</b>	<b>\$12,000 /yr</b>	<b>30-Nov-2016</b>	<b>1,496 cc</b>	<b>53,456 km</b>	<b>Hatchback</b>	<b>Available</b>
<b>Fuel Type:</b> Diesel (Euro 5 Engine and Above) PML Unit With Full Servicing Records At Agent, Excellent Condition And Accident Free, 100% Loan At Attractive Interest Rates Available, Call Us Now For Viewing Or Discussion At Your Convenience. Posted: 19-Aug-2021 Tags: 2016 BMW 116d, BMW 116d, BMW, 116d								
	<b>BMW 1 Series 116d</b>	-	N.A	<b>30-Nov-2016</b>	<b>1,496 cc</b>	-	<b>Hatchback</b>	<b>SOLD</b>
<b>Fuel Type:</b> Diesel (Euro 5 Engine and Above) \$0 Downpayment, Full Loan Available. PML Unit With Full Service History With PML From Day 1. Active Agent Warranty Till Dec 2021. Lowest Depre In The Market. Immaculate Condition In & Out. 100% Accident Free, STA Evaluation Welcome To Assure Condition.... Bavarian Marques Pte Ltd Posted: 24-Jul-2021 Tags: 2016 BMW 116d, BMW 116d, BMW, 116d								
	<b>Auto Spritze Pte Ltd - Specialist for Bmw Car repair, servicing &amp; maintenance</b> Auto Spritze is a European (Continental) car specialist that focuses on Mercedes-Benz, Volkswagen, Audi as well as BMW cars. Our team of 12 profession More Info about this shop							
	<b>BMW 1 Series 116d</b>	-	N.A	<b>29-Nov-2016</b>	<b>1,496 cc</b>	-	<b>Hatchback</b>	<b>SOLD</b>
<b>Fuel Type:</b> Diesel (Euro 5 Engine and Above) Low Mileage Done At 54,069 Km Only! 2 Owners! Fully Serviced And Maintained By PML Since Day 1 Till Now With Full Service Records Available For Proof Upon Viewing. 100% Accident Free With No Major Mishaps. Various Loan Options Catered To Your Needs! Free C... Posted: 15-Jul-2021 Tags: 2016 BMW 116d, BMW 116d, BMW, 116d								
	<b>BMW 1 Series 116d</b>	-	N.A	<b>22-Nov-2016</b>	<b>1,496 cc</b>	-	<b>Hatchback</b>	<b>SOLD</b>
<b>Fuel Type:</b> Diesel (Euro 5 Engine and Above) Very Low Mileage Done At 38,341Km Only! 2 Owners! Fully Serviced And Maintained By PML Since Day 1 Till Now With Full Service Records Available For Proof Upon Viewing. 100% Accident Free With No Major Mishaps. Various Loan Options Catered To Your Need... Posted: 18-Aug-2021 Tags: 2016 BMW 116d, BMW 116d, BMW, 116d								
	<b>BMW 1 Series 116d</b>	-	N.A	<b>16-Nov-2016</b>	<b>1,496 cc</b>	-	<b>Hatchback</b>	<b>SOLD</b>
<b>Fuel Type:</b> Diesel (Euro 5 Engine and Above) 1 Owner With Full Service History From Agent PML! Upgraded To 17" Sports Rims. 1st Batch Of 116d With Reverse Camera From Factory. Nice 3 Digit Carplate! Please Call For Appointment To View!								