

# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969

Our Ref : 305485596 Via Fax : Email  
Date : 06.09.21 Your Insured : SML 5983M  
Time of Fax : \_\_\_\_\_ Date of Acc : 03.09.21

Attn: Motor Claims Department

AIG

Dear Sirs

**SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH A 5727D**

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

◆ <b>Ms. Loke Wei Yieng (yy)</b>	<b>Tel: 62148355 or HP: 86285336</b>
◆ Juman Bin Masudin	Tel: 6214 8315 or HP: 9635 5305
◆ Lim Tien Sieng	Tel: 6214 8398 or HP: 9635 8546
◆ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006

**lokewy@sparkcarcare.com**  
**Fax no. 65468156**

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully



For Vice President  
Taxi Accident Repair

**COMFORT TRANSPORTATION PTE LTD**

## REPAIR ESTIMATE

**Vehicle No. : SHA5727D**

Date: 09.04.2021

Veh Reg Date: 24.11.2016

**Make** : HYUNDAI

**Insurance: AIG**

**Model** : I-40

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRT FENDER RH			\$663.00
1	FRT DOOR MIRROR RH			\$670.00
1	FRT DOOR RH			\$2,256.40
	SUB TOTAL			\$3,589.40
	LESS 20%			\$717.88
	DISCOUNTED TOTAL			\$2,871.52
	FRT DOOR ADVERTISEMENT LOGO RH			\$100.00
	FRT DOOR COMFORT LOGO RH			\$75.00
				\$175.00
	<b>Labour Charge</b>			
	PANEL BEATING			\$700.00
	SPRAY PAINTING CHARGE			\$750.00
	TRASFER OF DOOR			\$120.00
	TUFF KOTE			\$60.00
	CHECK WIRING AND LIGHTING			\$60.00
	TOTAL LABOUR			\$1,690.00
	ESTIMATE TOTAL			\$4,736.52

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.