

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHA5727D

Date: 09.04.2021

Veh Reg Date: 24.11.2016

Make : HYUNDAI

Insurance: AIG

Model : I-40

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRT FENDER RH			\$663.00
1	FRT DOOR MIRROR RH			\$670.00
1	FRT DOOR RH			\$2,256.40
	SUB TOTAL			\$3,589.40
	LESS 20%			\$717.88
	DISCOUNTED TOTAL			\$2,871.52
	FRT DOOR ADVERTISEMENT LOGO RH			\$100.00
	FRT DOOR COMFORT LOGO RH			\$75.00
				\$175.00
	Labour Charge			
	PANEL BEATING			\$700.00
	SPRAY PAINTING CHARGE			\$750.00
	TRASFER OF DOOR			\$120.00
	TUFF KOTE			\$60.00
	CHECK WIRING AND LIGHTING			\$60.00
	TOTAL LABOUR			\$1,690.00
	ESTIMATE TOTAL			\$4,736.52

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tharon Lkh
 tharon@lkhauto.com
 82235769
 6/9/21 1615
 3 days w/p
 L/S after repair photos

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 04.09.2021 10:09 Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4115680

JG NO 305485596

CUSTOMER

NAME COMFORT TRANSPORTATION PTE LTD
CUSTOMER NO 7010045
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
TEL NO 65508755 (O)

REGN NO SHA5727D

MILEAGE

MAKE HYUNDAI

FUEL

MODEL I-40

DATE/TIME IN 04.09.2021 08:40

YR OF MANU 24.11.2016

TARGET DATE

CHASSIS CODE KMHLB41UMHU096426

COMPLETION DATE/TIME

ACCOUNT CARD NO

JOB DESCRIPTION

Accident Date: 03.09.2021
NATURE: 3P 03.09.2021


S/NO

LABOR CODE

DESCRIPTION



AIG - SML 5983M



TAKE PHOTOGRAPH
BEFORE / AFTER
REPAIR WORKING

CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

knowledge Slip

Exit Pass

me:

Vehicle No.:

No.:

SHA5727D

title No.:

SHA5727D

YY

me of Service Advisor

Signature/Date

Name of Service Advisor

Date

be returned to Service Reception upon collection

To be kept by Security Guard