



Service Request Details

Claim

S1M03H5R

Reference

CS/ASM21009348/c 

Loss Date

2 September 2021

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

3 Sep 2021 10:54:02 AM

Request Date

6 September 2021

Due Date

13 September 2021

Services

Pre-Repair Survey

Actions

Next Step

Agree to perform service

[Decline Work](#)



Vehicle Information

Incident Vehicle Registration #
SLA8844G

Make
TPVD MG

Model
ZS EV AT

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

TEO Kitty

kitty.teo@axa.com.sg

Additional Instructions

- Messages1
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

New Message

TYPE

SENT




6/9/21 4:36 PM



BODY

Dear Kitty, Noted with thanks. Repairer arrange su...

↩

TYPE 


SENT 6/9/21 3:23 PM

FROM TEO Kitty

SUBJECT **Re:S1M03H5R**

BODY Hi Yan, H S Automotives Pte. Ltd. ...

↩

TYPE 

SENT 6/9/21 12:33 PM

FROM LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT **S1M03H5R**

BODY Dear Kitty,Please provide workshop detail. Thank y...

↩