

Steve (LKK)
8/9/21, 9.30am

W/L AL
3 dgs
L/S

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Lee Chen Sin
CLAIM DEPARTMENT
DID : 66547520
FAX :

Date : 06/09/2021

To : INDIA INTERNATIONAL INSURANCE PTE LTD
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : NG WEE YANG
: AIG ASIA PACIFIC INSURANCE PTE. LTD.

Certificate No : 2100457958-05

Accident Date : 01/09/2021

Vehicle No : SLA-9881-S

Make & Model : TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
<u>List Item</u>			
	RESTORE		
1	REAR BOOTLID X nn	75.52	
1	REAR BOOTLID EMBLEM CENTRE X nn	65.44	
1	REAR BOOTLID EMBLEM "COROLLA" X nn	65.44	
1	REAR BOOTLID EMBLEM "ALTIS" X nn	654.25	492 ✓
1	REAR BUMPER - nn	50.00	30 ✓
10	REAR BUMPER CLIPS - nc	84.62	
1	REAR BUMPER SIDE RETAINER LH - BR	84.62	
1	REAR BUMPER SIDE RETAINER RH - BR	384.55	
1	REAR BUMPER REINFORCEMENT ? X nn		

691.24
- 95%
518.43

Date : 06/09/2021

To : INDIA INTERNATIONAL INSURANCE PTE LTD
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : NG WEE YANG

: AIG ASIA PACIFIC INSURANCE PTE. LTD.

Certificate No : 2100457958-05

Accident Date : 01/09/2021

Vehicle No : SLA-9881-S

Make & Model : TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	REAR END PANEL X nn	553.64	
1	REAR END PANEL TOP GARNISH X nn	214.34	
1	SPARE TYRE PANEL X nn		
	Sub Total	2232.42	
	Discount 25% On Parts	(558.11)	
	<u>Special Nett Item</u>		
1	REVERSE SENSOR - Shaded	200.00	
1	END PANEL SEALANT X nn	40.00	

RESTORE

Date : 06/09/2021

To : INDIA INTERNATIONAL INSURANCE PTE LTD
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : NG WEE YANG

: AIG ASIA PACIFIC INSURANCE PTE. LTD.

Certificate No : 2100457958-05

Accident Date : 01/09/2021

Vehicle No : SLA-9881-S

Make & Model : TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT

Excess : 0.00 Add Excess : 0.00

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

Sub Total

240.00

Labour & Misc

LABOUR TO CARRY OUT REAR REPAIR
TO CHECK AND RECONNECT ALL NECESSARY WIRINGS
TO SPRAY PAINTING ON REAR AFFECTED AREA
SPRAY RUST PROOF ON AFFECTED AREA
TO DETACH & RENEW REVERSE SENSOR

800.00

200

35.00

30

700.00

200

40.00

X

60.00

30

460

P- 518.43

M- 200

L- 460

1178.43

LIS- 942.74

= 950

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PAGE : 3