

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Lee Chen Sin
CLAIM DEPARTMENT
DID : 66547520
FAX :

Date : 06/09/2021

To : **INDIA INTERNATIONAL INSURANCE PTE LTD**
ESTIMATION

Attn : **Motor Claim Department** FAX :

Owner : NG WEE YANG
: AIG ASIA PACIFIC INSURANCE PTE. LTD.
Certificate No : 2100457958-05 Accident Date : 01/09/2021
Vehicle No : SLA-9881-S Make & Model : TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT

ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
List Item			
1	REAR BOOTLID	RESTORE	
1	REAR BOOTLID EMBLEM CENTRE	75.52	
1	REAR BOOTLID EMBLEM "COROLLA"	65.44	
1	REAR BOOTLID EMBLEM "ALTIS"	65.44	
1	REAR BUMPER	654.25	
10	REAR BUMPER CLIPS	50.00	
1	REAR BUMPER SIDE RETAINER LH	84.62	
1	REAR BUMPER SIDE RETAINER RH	84.62	
1	REAR BUMPER REINFORCEMENT	384.55	

Date : 06/09/2021

To : **INDIA INTERNATIONAL INSURANCE PTE LTD**
ESTIMATION

Attn : **Motor Claim Department**

FAX :

Owner : NG WEE YANG

: AIG ASIA PACIFIC INSURANCE PTE. LTD.

Certificate No : 2100457958-05

Accident Date : 01/09/2021

Vehicle No : SLA-9881-S

Make & Model : TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	REAR END PANEL	553.64	
1	REAR END PANEL TOP GARNISH	214.34	
1	SPARE TYRE PANEL	RESTORE	
	Sub Total	2232.42	
	Discount 25% On Parts	(558.11)	
	<u>Special Nett Item</u>		
1	REVERSE SENSOR	200.00	
1	END PANEL SEALANT	40.00	

Date : 06/09/2021

To : **INDIA INTERNATIONAL INSURANCE PTE LTD**
ESTIMATION

Attn : **Motor Claim Department**

FAX :

Owner : NG WEE YANG

: AIG ASIA PACIFIC INSURANCE PTE. LTD.

Certificate No : 2100457958-05

Accident Date : 01/09/2021

Vehicle No : SLA-9881-S

Make & Model : TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	240.00	
	<u>Labour & Misc</u>		
	LABOUR TO CARRY OUT REAR REPAIR	800.00	
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	35.00	
	TO SPRAY PAINTING ON REAR AFFECTED AREA	700.00	
	SPRAY RUST PROOF ON AFFECTED AREA	40.00	
	TO DETACH & RENEW REVERSE SENSOR	60.00	

Date : 06/09/2021

To : **INDIA INTERNATIONAL INSURANCE PTE LTD**
ESTIMATION

Attn : **Motor Claim Department** FAX :

Owner : NG WEE YANG
: AIG ASIA PACIFIC INSURANCE PTE. LTD.
Certificate No : 2100457958-05 Accident Date : 01/09/2021
Vehicle No : SLA-9881-S Make & Model : TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT

ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	1635.00	

3,549.32

Remarks:

SUB TOTAL
GST 7.0 % 248.45
TOTAL 3,797.77

Surveyor's name: _____

Principal's name: NG WEE YANG

Survey Date & Time: _____