

Steve (LKK)
8/9/21, 9.31am

W/L P/L
Ry AL sy
3 dgy
L/S

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Lee Chen Sin
CLAIM DEPARTMENT
DID : 66547520
FAX :

Date : 06/09/2021

To : INDIA INTERNATIONAL INSURANCE PTE LTD
ESTIMATION

Attn : Motor Claim Department FAX :

Owner : NG WEE YANG
: AIG ASIA PACIFIC INSURANCE PTE. LTD.

Certificate No : 2100457958-05 Accident Date : 01/09/2021

Vehicle No : SLA-9881-S Make & Model : TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

List Item

1	REAR BOOTLID X	RESTORE	
1	REAR BOOTLID EMBLEM CENTRE X		75.52
1	REAR BOOTLID EMBLEM "COROLLA" X		65.44
1	REAR BOOTLID EMBLEM "ALTIS" X		65.44
1	REAR BUMPER - DD		654.25
10	REAR BUMPER CLIPS - MC	30	50.00
1	REAR BUMPER SIDE RETAINER LH - GR		84.62
1	REAR BUMPER SIDE RETAINER RH - GR		84.62
1	REAR BUMPER REINFORCEMENT ?		384.55

Date : 06/09/2021

To : **INDIA INTERNATIONAL INSURANCE PTE LTD**
ESTIMATION

Attn : **Motor Claim Department**

FAX :

Owner : NG WEE YANG

: AIG ASIA PACIFIC INSURANCE PTE. LTD.

Certificate No : 2100457958-05

Accident Date : 01/09/2021

Vehicle No : SLA-9881-S

Make & Model : TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	REAR END PANEL X	553.64	
1	REAR END PANEL TOP GARNISH X	214.34	
1	SPARE TYRE PANEL X	RESTORE	
	Sub Total	2232.42	
	Discount 25% On Parts	(558.11)	
	<u>Special Nett Item</u>		
1	REVERSE SENSOR - Shaded	200.00	
1	END PANEL SEALANT X	40.00	

Date : 06/09/2021

To : INDIA INTERNATIONAL INSURANCE PTE LTD
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : NG WEE YANG

: AIG ASIA PACIFIC INSURANCE PTE. LTD.

Certificate No : 2100457958-05

Accident Date : 01/09/2021

Vehicle No : SLA-9881-S

Make & Model : TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	240.00	
	<u>Labour & Misc</u>		
	LABOUR TO CARRY OUT REAR REPAIR	800.00	200
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	35.00	30
	TO SPRAY PAINTING ON REAR AFFECTED AREA	700.00	200
	SPRAY RUST PROOF ON AFFECTED AREA	40.00	X
	TO DETACH & RENEW REVERSE SENSOR	60.00	30

Date : 06/09/2021

To : INDIA INTERNATIONAL INSURANCE PTE LTD
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : NG WEE YANG

: AIG ASIA PACIFIC INSURANCE PTE. LTD.

Certificate No : 2100457958-05

Accident Date : 01/09/2021

Vehicle No : SLA-9881-S

Make & Model : TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	1635.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Remarks: Acknowledged by Repairer

Signature:

Date:

3,549.32

SUB TOTAL

GST 7.0 % 248.45

TOTAL 3,797.77

Surveyor's name: _____

Principal's name: NG WEE YANG

Survey Date & Time: _____

PAGE : 4