SN0821970003 / National Assessment Centre Services [159721] ENTRY DATE & TIME: 07/09/2021 11:53 (SGT) SUBMITTED BY: Rosli Bin Abdul Wahab VERSION: 1 (07/09/2021 11:53 (SGT))

# **SINGAPORE ACCIDENT STATEMENT**

#### **IMPORTANT NOTICE**

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

  4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of this is form by instrained companies.
   5. Any false reporting may be referred to the Police for investigation.
   6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### **ACCIDENT STATEMENT**

Date of Submission 07/09/2021 11:53 (SGT) Date of Accident 03/09/2021 17:00 (SGT) Exact Location of Accident Tampines Ave 2, Singapore Additional Location Information **TURNING LEFT INTO TAMPINES STREET 32** Country/State of Loss Singapore

### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number SI X59017

INSURED/POLICYHOLDER

Is company? No Name Of Registered Owner ANG HWEE YONG NRIC No. SXXXX345E

Email Address ahyonggang@hotmail.com Mobile Phone No (Phone) +65-97831245 Alternative Phone No

+65-97831245

VEHICLE PARTICULARS

Manufacturer Subaru Model Forester Variant

Exact purpose for which vehicle was being used at time of

accident Private use

Are you claiming under your own insurance policy for repair to your vehicle?

No - Claiming third party Vehicle Category Private car Transmission Auto CC 1995

**INSURANCE COMPANY** 

Name of Insurance Company AIG Asia Pacific Insurance Pte. Ltd. Type of Coverage Comprehensive

Fleet Policy

Policy Number 1800033019-03

Cover Note Number

DRIVER

Name of Driver ANG HWEE YONG NRIC No. SXXXX345E

Date Of Birth 16/02/1963 Occupation Indoor Date Of Driving Pass 13/02/1995 Driving experience 26 YEARS AND 7 MONTHS Gender Mobile Number (Phone) +65-97831245 Alt. Phone Number +65-97831245 Email Address ahyonggang@hotmail.com Address **BLK 488 TAMPINES STREET 45 #02-141** Address complement Postcode 521488 Is the driver the policyholder? Yes If No. Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Hit and run / Vandalism / Damaged whilst parked Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? Nο PASSENGER 1 Name AH LIAN Gender Female PASSENGER 2 Name **BENG KIAT** Gender Male PASSENGER 3 Name JIN JING Gender Female PASSENGER 4 Name AH HONG Gender DETAILS OF POLICE ACTION Was the accident reported to the police? Yes Police Station Name Tampines North Neighbourhood Police Post Police Station Phone No (Phone) +65-18007818999 Alt. Police Station Phone No (Fax) +65-67838603 Police Station Address Blk 461 Tampines Street 44 #01-56 Singapore 520461 Was notice of intended Prosecution given? If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

### ATTACHMENT(S)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

Reasons for not uploading a video of the accident

Was there any audio recorded?

No

# **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	SG3088R
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Bus
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	_

SKETCH PLAN			
		ंत्रिं हिंह	
	1	901	
	Paris Carried Street Warrant Control		
VEH ATI SLX 590	12	1	
VEH B: 59308	RRI		
VEH BO SHOW			
Control of the Contro			
		TANGENES S	732
DESCRIBE CIRCUMSTANCES		I a	
AS IRR	POLICE REPO	e7 /20210903/2	7060
			/
			/
		/	/
		/	
		/	
DECLARATION			
	ticulars are true in every respect.	/.	
$\mathcal{M}$	$\times$	/2/ml	
		an 0/19/2	021
Policyholder's gnature Date & Time:	Driver's Signature (If driver is not the policyholder)	Reporting Centre Personnel's Sign Name:	nature
wate & Hille:	Date & Time:	NRIC/FIN No.:	



















T/2/2/10903/2/106

police Station Of Origin: Tampines North NPP 461 Tampines Street 44 #01-56 SINGAPORE 520461 Tel No: 1800-7818999

1 of 3 Report No. T/20210903/2106

Anyone conveyed by

ambulance:

No

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 03/09/2021 19:30		Made:	Vide Report No.:	Station Diary No.; 49
Informa	nt's Partici	ulars		
Mary State State State State	Informant: VEE YONG		Address: APT BLK 488B TAMPINES S' 521488	TREET 45 #02-141 SINGAPORE
ID Type NRIC NO	/ ID No.: D / S158634	45E	Contact No.: Home/Office: Mobile: 97831245	
National SINGAP	ity: ORE CITIZ	'EN	Email:	
Sex: Male	Age: 58	Date of Birth: 16/02/1963	: Type of Informant:	
Race: Chinese			Language: English	Institution / School Name:
Occupation: OPERATION MANAGER		AGER	Driving Licence Information: Class:	Date of Expiry:

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 03/09/2021 17:00	Type of Location X-Junction
Location:				
TAMPINES A	VENUE 2			
Weather: Clear		Road Surface; Dry		Road Speed Limit:

Details of V	ehicle Invo	ved		the party sees		
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenge
SLX5901Z	Car	SUBARU	FORESTER 2.0I-L CVT AWD SR	Silver		4

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLX5901Z	AIG ASIA PACIFIC INSURANCE PTE,	1800033019-03	31/03/2021	30/03/2022

Type of Collision:

Moving Vehicle Against - Others



T/20210903/2106

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461 CONTINUATION OF REPORT

Report No. T/20210903/2106

2013

Tel No: 1800-7818999

Details of Person Any Pedestrian In				
No. of Pedestrian		Use of	Pedestrian C	rossing: NA
Driver				A CONTRACTOR OF THE PARTY OF TH
Name	ANG HWEE YONG	216	ID No.	S1586345E
Related Vehicle	SLX5901Z (Car)		Contact	No. 97831245
Hospital/Clinic	NIL		Class of Driving Licence Expiry D	& Date of Expiry: NIL
Date Treatment	NIL	Date D	ischarge N	
No. of Days gran	ted Medical Leave   NIL	Degree	e of Injury N	IIL CONTRACTOR OF THE PARTY OF

#### Brief Details.

On 03/09/2021 at about 1700hrs, I was driving my car (SLX5901Z) along Tampines Avenue 2. I was about to turn left into Tampines Street 32, but I came to a stop as there were pedestrian crossing the road.

While waiting for the pedestrian to cross, I then noticed a bus (Service 38) that was behind my car filtered to the next lane (right side) and started to drove off. I felt a sudden jerk and realised that the mentioned bus had knocked the rear right of my car. I horned, and noticed that the bus had slowed down, but not long after, the bus driver then drove off.

I wish to state that I do have an in-car camera installed in my car. However, only the front in-car camera is in function. Thus, I do not have the bus plate number. I wish to add on that neither my passengers nor I sustained any injury.

