



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Page No. 1

Our Ref : WH0820				
Vehicle No. : SLU9480K				
Make & Model : HYUNDAI ELANTRA AD 1.6				
QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Bonnet / 00		1911.00	
2	Bonnet hinge LH/RH @2*\$55 X		110.00	
1	Front fender RH / 00		1227.00	
1	Front bumper / BR		500.00	
2	Front bumper side retainer LH/RH @2*\$30 - BR		60.00	
1	Headlamp RH - BR		1200.00	
1	Headlamp lower bracket RH ?		30.00	
1	Support Panel (Repair refer to labor) X		0.00	
Part Items Total:			5038.00	
			-20% -1007.60	
			4030.40	
SPECIAL NETT ITEMS				
1	Front bumper clips / MK		35.00 20	
2	Front fender Shield clips X		25.00	
3	Center Grille Clips X		30.00	
4	Front bumper rivets / MK		60.00 10	
SN Items Total:			150.00	
Total Parts:			4180.40	



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref	: WH0820
Vehicle No.	: SLU9480K
Make & Model	: HYUNDAI ELANTRA AD 1.6

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1000.00	400 500
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1000.00	600
3	To perform anti-rust treatment on affected areas	60.00	30
4	To remove and refix wiring system at accident damaged area and check for all electrical proper function	60.00	30
5	To remove and re-sealing of Off peak car licence plate.	120.00	100
6	To remove, replace and focus headlamp beam	60.00	30
Labour Total :		2300.00	
TOTAL (PARTS & LABOUR):		6480.40	

Steve (LKK)
8/9/21, 1.00pm

W/L M
5 dys
L/S
My AL sy

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	04/09/2021 12:32 (SGT)
Date of Accident	31/08/2021 13:15 (SGT)
Exact Location of Accident	Near 164 Bukit Batok Street 11, Singapore 650163
Additional Location Information	BLK 164 BUKIT BATOK ST 11 (OPEN SPACE CAR PARK)
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLU9480K
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	ANG JIONG HUI
NRIC No	SXXXX067J
Email Address	JIONGHUI86@LIVE.COM
Mobile Phone No	(Phone) +65-96641914
Alternative Phone No	+65-96641914

VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	Elantra
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1591

INSURANCE COMPANY

Name of Insurance Company	Direct Asia Insurance (Singapore) Pte Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	MT/00651661/01
Cover Note Number	-

DRIVER

Name of Driver	ANG JIONG HUI
NRIC No	SXXXX067J

Date Of Birth 01/02/1986
 Occupation Indoor
 Date Of Driving Pass 22/12/2011
 Driving experience 9 YEARS AND 8 MONTHS
 Gender Male
 Mobile Number (Phone) +65-96641914
 Alt. Phone Number +65-96641914
 Email Address JIONGHUI86@LIVE.COM
 Address BLK 452A BUKIT BATOK WEST AVE 6
 Address complement #21-735
 Postcode 651452
 Is the driver the policyholder? Yes
 If No, Relationship of the Driver with the Insured -
 Does Driver Own Other Vehicles? No
 Vehicle Registration Number of Other Vehicle Owned by Driver -
 Insurance Company of Other Vehicle Owned by Driver -

a Company Name
 Of Damage
 of property damaged
 of Passenger (Includ

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collided into Parked Vehicle
 Weather Conditions Clear
 Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
 Number of vehicles involved in the accident 2
 Was anybody injured in the Accident? No
 Was any injured conveyed to hospital by ambulance? -
 Was any other vehicle or property damaged? Yes
 Number of Passengers (Including Driver) 0
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
 Was notice of intended Prosecution given? No
 If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO THE SKETCH PLAN FOR ACCIDENT DETAILS.

ATTACHMENT(S)

Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? No
 Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBE8901Y
 Vehicle Manufacturer Toyota
 Vehicle Model Dyna
 Vehicle Variant -
 Vehicle Colour -
 Vehicle Category -
 Name of Driver Commercial vehicle
 Contact Number -
 Address (Phone) +65-83453532
 Address complement -

Company Name	-
Of Damage	-
Of property damaged in accident	-
Of Passenger (Including Driver)	-

AXA Insurance Pte Ltd

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



Vehicle A: SLV 9450K

BLACK BUCKET BAYON ST 11 (OPEN SPACE CAR PARK)




Describe Circumstances of the Accident


On 31 August 2021 at about 1.15pm, my car was parked at the side of the road below Bait Bait Bait 164 Street 11. When I came back to my vehicle, I found damages to my vehicle. The driver of the vehicle who hit my car was drunk and asked me to clean his insurance and we exchanged photos of the damages and exchanged contacts.

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

Require PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 067J

Vehicle Details

Vehicle No.: SLU9480K
Vehicle to be Exported: No
Intended Deregistration Date: 30 Sep 2021
Vehicle Make: HYUNDAI
Vehicle Model: ELANTRA AD 1.6 GLS AT
Primary Colour: Silver
Manufacturing Year: 2017
Engine No.: G4FGHU830248
Chassis No.: KMHD841CMJU593185
Maximum Power Output: 93.8 kW (125 bhp)
Open Market Value: \$11,900.00
Original Registration Date: 19 Dec 2017
First Registration Date: 19 Dec 2017
Transfer Count: 0
Actual ARF Paid: \$11,900.00

OPC Cash Rebate Details

OPC Cash Rebate Eligibility: Yes (w.e.f 16 Jun 2018)
OPC Cash Rebate Eligibility Expiry Date: 18 Dec 2027
OPC Cash Rebate Amount: \$641.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 18 Dec 2027
PARF Rebate Amount: \$8,925.00

Intended COE Rebate Details

COE Expiry Date: 18 Dec 2027
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$46,791.00
COE Rebate Amount: \$29,080.00
Total Rebate Amount: \$38,005.00

The information contained herein is correct as at 04 Sep 2021

OK