

(08/11/13) wef

ASS. REC. BY:

REF:

CS/CTI 21009393/Ritz

2082

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLU 8913K

at Workshop m/s Auto Insurance

of 6, magsunh LN

Insured: CTI

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

57K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLU 8913K Yr Regn: 2017 / DGL

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

HYUNDAI ELANTRA ADI-645.c.c 1591

Colour:

Grey

Sp. Reading:

37842 254317

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rim or

Tyre Size:

F:

R:

205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair limit - 20k

finalise amount at \$ 3,114.55 (Before GST) and 05 repair days.

RED: 2301.60 ; 42%

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

): S + RS, SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Auto Insure Pte. Ltd
Marsiling Lane
739145



Insurer Reference: SLU8913K
Repairer Reference: M2933 / SLU8913K
Date calculated: 02/09/2021 12:07 PM

Full Report
Registration: SLU8913K
Printed: 02/09/2021 12:07 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Min Seng Chong	Currency:	SGD
Claim Reference:	SLU8913K	Date of Incident:	27/08/21
Estimated Repair Time:	6	Hire Car Start:	
Actual Repair Days:	6	Hire Car End:	

Vehicle Details

Vehicle	
Manufacturer:	HYUNDAI
Model:	ELANTRA (AD)
Sub Model:	BASE MODEL
Model Sheet Number:	30 92 01
Registration:	SLU8913K
VIN number:	KMHD841CMJU593087
Odometer:	37842
Model Specs	
1.6 LTR 94 KW	TWO COAT METALLIC

Vehicle Condition


Vehicle Status

Accident Damage:

Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Tyres Condition

Tyre Brand	Tread (Left Middle), mm	Tread (Left Outer), mm	Tread (Left Inner), mm	Tread (Right Inner), mm	Tread (Right Outer), mm	Tread (Right Middle), mm	Condition
------------	----------------------------	---------------------------	---------------------------	----------------------------	----------------------------	-----------------------------	-----------

Spare Tyre Brand Tread (Spare), mm

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
18600A00	ADJUST HEADLAMPS		3.0	12.60
NO NUMBER	R + R FRONT PANEL		16.0	67.20
86510R00	RENEW FRONT BUMPER		8.0	33.60
	INCLUDES: R + R FRONT BUMPER, GRILLE AND NECESSARY ATTACHED PARTS			
66300R00)	R + R L/F WING		4.0	16.80
	INCLUDES: R + R HEADLAMP AND NECESSARY ATTACHED PARTS			
	DOES NOT INCLUDE: R + R FRONT BUMPER, ADJUST HEADLAMP			
66300R5A)	R + R R/F WING		4.0	16.80
	INCLUDES: R + R HEADLAMP AND NECESSARY ATTACHED PARTS			
	DOES NOT INCLUDE: R + R FRONT BUMPER, ADJUST HEADLAMP			
86520R00	RENEW REAR BUMPER		9.0	37.80
	INCLUDES: R + R OUTER TAIL LAMPS AND NECESSARY ATTACHED PARTS			

	Description	WU	Price SGD
R00	RENEW BADGE "HYUNDAI"	2.0	8.40
OR00 ZAX	RENEW TYPE BADGE BOOTLID	3.0	12.60
30R00)	R + R REAR BUMPER CARRIER	3.0	12.60
100R00	R + R AIR CLEANER CPL	3.0	12.60
5300R00)	R + R RADIATOR	7.0	29.40
NO NUMBER	DRAIN/REFILL COOLING SYSTEM	3.0	12.60
2931	BOOTLID REPAIR	10.0*	42.00

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	7.50	75.0	315.00
Total of Labour			315.00

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	FRONT BUMPER NEW PART PAINT K1R	10.0
	FRT TOWING EYE COVER NEW PART PAINT K1R	3.0
	REAR BUMPER NEW PART PAINT K1R	8.0
	BOOTLID REPAIR PAINTING >50%	20.0

Paint Material Per Part

Code	Description	Price SGD
0283	FRONT BUMPER NEW PART PAINT K1R	47.23
0284	FRT TOWING EYE COVER NEW PART PAINT K1R	0.49
2583	REAR BUMPER NEW PART PAINT K1R	35.42
2931	BOOTLID REPAIR PAINTING >50%	22.91

Labour Cost - Paint	Hrs	WU	Price SGD
Factor			42.00 SGD/h
Time Paint		41.0	
Preparation Main Work Metal	2.10	21.0	88.20
Preparation Comp. Work Plastic	0.50	5.0	21.00
Total	10 WU/h	67.0	281.40

Material Cost - Paint	Price SGD
New Part Painting - Plastic K1R	83.14
Repair Painting	22.91
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	133.15

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-06-01 Price SGD
3015	BADGE "HYUNDAI"	86321F2000	Original	25.00
3014	BADGE MODEL	86315F2000	Original	30.00

	Description ?	Part Number	Part Source	Price SGD
	CONDENSER ?	97606F2000	Original	215.00
	FRONT BUMPER de / ?	86510F2000	Original	265.00
	FRONT IMPACT DAMPER	86520F2000	Original	66.00
	FRONT PANEL CPL cga /	64101F2000	Original	300.00
	FRT BUMPER REINF ?	86571F2000	Original	135.00
	FRT BUMPER SUPPORT ?	64900F2010	Original	240.00
	FRT TOWING EYE COVER	86588F2000at /	Original	15.00
	GRILLE ca /	86350F2000	Original	540.00
	L/F INN BUMPER BRKT ?	86553F2000ne /	Original	22.00
	LEFT HEADLAMP ASSY	92101F2030	Original	695.00
	R/F INN BUMPER BRKT ?	86554F2000ne /	Original	22.00
	R/R REFLECTOR ?	92406F2000	Original	36.00
	REAR BUMPER de /	86611F2000	Original	240.00
	REAR BUMPER SPOILER	86612F2000sua /	Original	135.00
	REAR BUMPER SUPPORT	86631F2020 ?	Original	240.00
	RIGHT HEADLAMP ASSY	92102F2030 ?	Original	695.00

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings
Subtotal
Addition(+10.00%)

0.00
3,916.00
391.60

Total

4,307.60

Extras

Code	Description	Price SGD
1000	NO PLATE WITH HOLDER FRONT l /	35 80.00*
1001	BUMPER CLIPS FRONT ne /	30 50.00*
1002	AIR CON GAS FRONT 2 ne /	60 100.00*
1003	BUMPER CLIPS REAR ne /	30 50.00*
Total Extras		280.00

Final Calculation

	SGD	SGD
Parts		
Addition(+10.00%)	3,916.00	
Total Parts	391.60	4,307.60
Labour Time Base 10 WU/h		
Total 75.0 WU X 42.00 SGD/h	315.00	
Total of Labour		315.00
Total Of Extras		280.00
Paint Work Time Base 10 WU/h		
Labour Cost 67.0 WU X 42.00 SGD/h	281.40	
Material Cost	133.15	
Total Paint Including Material		414.55
Repair Cost Excludes GST		5,317.15
GST (+7.00%)		372.20
Repair Cost Included GST		5,689.35

5416.15

Comments

- USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Pass

Hy 900600 68

5 days

HS

07/09/21 @ 1330

Resurvey after repair

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 28/08/2021 12:08 (SGT)
Date of Accident 27/08/2021 16:00 (SGT)
Exact Location of Accident PIE, Singapore
Additional Location Information TWDS TUAS
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLU8913K

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner LIM KWANG CHOY
NRIC No SXXXXX708Z
Email Address ALVIN.LIM@ANRITSU.COM
Mobile Phone No (Phone) +65-97325776
Alternative Phone No +65-97325776

VEHICLE PARTICULARS

Manufacturer Hyundai
Model Elantra
Variant AD 1.6 GLS AT
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1591

INSURANCE COMPANY

Name of Insurance Company Direct Asia Insurance (Singapore) Pte Ltd
Type of Coverage Comprehensive
Fleet Policy No
Policy Number MT/00710408
Cover Note Number -

DRIVER

Birth Date	03/12/1964
Location	Indoor
Driving Pass	18/09/1985
Experience	35 YEARS AND 11 MONTHS
Gender	Male
Mobile Number	(Phone) +65-97325776
Phone Number	+65-97325776
Email Address	ALVIN.LIM@ANRITSU.COM
Address	BLK 845 JURONG WEST ST 81 #14-229
Address complement	-
Postcode	640845
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	4
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMZ133J
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-

Company Name -
Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

DETAILS OF OTHER VEHICLE PROPERTY 2


Vehicle Registration Number SFP109R
Vehicle Manufacturer -
Vehicle Model -
Vehicle Variant -
Vehicle Colour -
Vehicle Category Private car
Name of Driver -
Contact Number -
Address -
Address complement -
Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number UNKNOWN
Vehicle Manufacturer -
Vehicle Model -
Vehicle Variant -
Vehicle Colour -
Vehicle Category Taxi
Name of Driver -
Contact Number -
Address -
Address complement -
Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

SKETCH PLAN

PIE



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 27/08/2011 at 1600hrs, I was travelling along PIE Tnds Mas, I was in the first lane when the vehicle in front brake. I follow suit. Moments later I felt an impact from the rear and realized vehicle B had collided onto my vehicle.

I wish to state that the impact caused by vehicle B had pushed me forward to hit vehicle C and vehicle C hit onto vehicle D. It was a 4 cars collision.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel Signature
Name:
NRIC/FIN No.:

Apply PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 708Z

Vehicle Details

Vehicle No.: SLU8913K
Vehicle to be Exported: No
Intended Deregistration Date: 01 Sep 2021
Vehicle Make: HYUNDAI
Vehicle Model: ELANTRA AD 1.6 GLS AT
Primary Colour: Silver
Manufacturing Year: 2017
Engine No.: G4FGHU835944
Chassis No.: KMHD841CMJU593087
Maximum Power Output: 93.8 kW (125 bhp)
Open Market Value: \$13,873.00
Original Registration Date: 18 Dec 2017
First Registration Date: 18 Dec 2017
Transfer Count: 0
Actual ARF Paid: \$13,873.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 17 Dec 2027
PARF Rebate Amount: \$10,404.00

Intended COE Rebate Details

COE Expiry Date: 17 Dec 2027
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$41,617.00
COE Rebate Amount: \$26,189.00
Total Rebate Amount: \$36,593.00

The information contained herein is correct as at 01 Sep 2021

OK

Hyundai Elantra 1.6A GLS

Overview

Financial

Accessories

Similar

Research

Photos

Map

IBKW
AUTOMOBILE



Price **\$56,800**

Depreciation ?	\$8,350 /yr View models with similar depre	Reg Date	13-Nov-2017 (6yrs 2mths 5days COE left)
-----------------------	---	-----------------	--

Mileage	73,000 km (19.1k /yr)	Manufactured ?	2017
----------------	-----------------------	-----------------------	------

[finalise amount at \\$ 3,114.55 \(Before GST\) and 05 repair days.](#)

Road Tax ?	RED: \$738 /yr	Transmission	Auto
-------------------	----------------	---------------------	------

Dereg Value ?	\$34,979 as of today (change)	OMV ?	\$10,360
----------------------	-------------------------------	--------------	----------

COE ?	\$44,002	ARF ?	\$10,360
--------------	----------	--------------	----------

Engine Cap	1,591 cc	Power	93.8 kW (125 bhp)
-------------------	----------	--------------	-------------------

Curb Weight ?	1,345 kg	No. of Owners ?	1
----------------------	----------	------------------------	---