



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21009399/Kvf3n2 Date: 04/10/2021	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLP 9179H	Veh. Inspected	SLS 8969K	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10011554/HA	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	07/09/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	RU31226125	Colour	METALLIC GREY	
Odometer	306610 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	TRISTAR	9 mm	
L/H Front Tyre	215/60 R16	TRISTAR	9 mm	
R/H Rear Tyre	215/60 R16	HABILEAD	7 mm	
L/H Rear Tyre	215/60 R16	HABILEAD	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/09/2021	Inspection Date	27/09/2021	
Survey held at	BLK 176 SIN MING DRIVE #01-14, SIN MING AUTOCARE			
Repairer	ESTEEM PERFORMANCE PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	