

ASS. REC. BY:

REF:

LPC / 210094091kg

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

	
N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 1 B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMP 72207 Yr Regn: 10.1.19Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Altis c.c. 1598Colour: N. Silver A/C: Insured / Std / NI / NASp. Reading: 167267 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NR053REH 604598923Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rlm / STD A/Rlm orTyre Size: F: 165/60R15 205/55R16Greenlander

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mmL/Bal. 8 mmD.O.A. 5/9/21

Survey held at

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 9 mmL/Bal. 9 mmD.O.I. 7/9/2021

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4/11/21 87432.80 Cash

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S - P.S. SI

FURTHER

Others

Report Format :

Lump Sum / I.B.I: (\$

TOTAL