



1 of 3

Report No. T/20210826/2110

Police Station Of Origin: Jurong West N.P.C 700 Corporation Road SINGAPORE 649818 Tel No: 1800-2689999

REPORT	OF A TRAFFI	CACCIDENT			
	Date/Time Report Made: 26/08/2021 21:47		Vide Report No.:	Station Diary No.: 164	
Informa	nt's Partic	ulars			
Name of CHUA Z	Informant:		Address:		
ID Type / ID No.: FIN NO / G1198712K			Contact No.: Home/Office:	Mobile: 93911902	
Nationality: MALAYSIAN			Email:		
Sex: Male	Age:	Date of Birth: 15/10/1997	Type of Informant: Rider		
Race: Chinese			Language:	Institution / School Name:	
Occupation: WAREHOUSE ASSISTANT			Driving Licence Information: Class:	Date of Expiry:	

P. S.	Injury	Drink	Date/Time of	Type of Location:
Type of Accident:	Attended by Police	Drive: No	Accident: 26/08/2021 07:30	1-Junction
Location:	A CONTRACTOR OF STATE			
CHIN BEE DRI	VE			
\Meather		Road Surface:		Road Speed Limit:
Weather: Clear		Dry		Road Speed Limit:

odel	Color	Condition	No of Passenge
		Seriously	0
		Seriously	0
			Seriously Damaged Seriously Damaged

Details of Person Involved			
Any Pedestrian Involved: No	The Annual Consoling MA		
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA		



No. of Days granted Medical Leave



Serious

2 of 3

Report No. T/20210826/2110

Police Station Of Origin: Jurong West N.P.C 700 Corporation Road SINGAPORE 649818 CONTINUATION OF REPORT Tel No: 1800-2689999

Rider		BISOURS IN A	LIDNA		G1198712K
Name	CHUA ZHI WEI		ID No.		G119071210
Related Vehicle	JRU6328 (Motorcycle)		Contact No.		93911902
Hospital/Clinic	NG TENG FONG GENERAL F	IOSPITAL	Class Driving Licent Expiry	g ce &	Class: NIL Date of Expiry: NIL
Data Treatment	26/08/2021	Date Dis	charge	NIL	
Date Treatment	AUTIEUR ZO/OO/ZOZI			Corio	NIC.

Degree of Injury

## Brief Details.

On 26/08/2021 at about 0730hrs, I was riding V1) JRU6328 along Chin Bee Dr towards Jln Boon Lay. As I was approaching the junction of Quality Road, I noticed V2) YP7860H inching out from the stop line. After which, I slowed down my motorbike and to allow V2 to filter out. After slowing down, I noticed V2 was not moving thus, I sped up to continue my journey. Suddenly, V2 turned out and I was unable to stop in time. Thus, collided into the front right door of V2. I lost my balance and fell onto my right. I suffered abrasions on both my shoulders and right knee and also some swollenness on my right knee and calf area.

05

From the accident, V1 was badly damaged and unable to start. V2's front right door was damaged as well.

I was given MC rom 26/08/2021 to 30/08/2021.

V2's driver only provide me his contact number, 98416733 however, he did not provide me his name and particulars.

During the accident, there were a few cars behind V2 and one of the driver informed that he has a in-car camera footage of the accident however he did not gave me his contact number.





3 of 3

Police Station Of Origin: Jurong West N.P.C 700 Corporation Road SINGAPORE 649818 Tel No: 1800-2689999

Report No. T/20210826/2110

**CONTINUATION OF REPORT** 

## Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the <u>report number</u> as reference.

Signature Of Officer Recording The Report:  J / Sgt 2 CHEW WEI XIANG	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 26/08/2021 21:47
Officer In Charge Of Case: TP / GIT / Sr <sub>I</sub> Staff Sgt LIM ENG KUAN, CLARENCE	Classification Of Case:
Contact No.: 65476256 SN 126  Authentication Stamp  NP168 Signature:	
Singapore Police Force	