MEF: 05/CT/21009438/TIVC ASSIGNMENT SG 1849A · Yr Regn: / 2019 Date: From: Type: M.Car / M.Cycle / Bus / Van / Lorry /. Taxi / Prime Mover / Estimated Cost: OD ITP/WS/TP RES/OD RES/EVA/INV/MV Truck / Trailer or . c.c 10518 MAN To Inspect Vehicle No: at Workshop m/s A/C: Insured / Std / NI / NA T/Radlo; Insured / Std / NI / NA Sp.Reading SGJ 4056C Insured: Eng/No: WMAA22ZZZ3T DMPCSNW00077992001 Policy No. Claims No. SNM21D201087/C03 Gen. Cond: Good / Fair / Poor / Burnt Steering: Inorder / Jammed / Leaked / Burnt or Sum Insured: Brake: Ingrder/ Jammed / Leaked / Burnt or (Client's Record) Modi: NH S/Rim / STD A/Rim or Make of Veh: Tyre Size: (Policy Condition) BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / NIS OIS Remark: The yeh had commenced its Continental repair at the time of inspection. TOYO/YOKO or Front Bal. or Market Value: R/Bal. R/Bal. Consistent? : Yes or No IDAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: D.O.I. D.O.A. 20/2/21 Res.: Yes or No days Est. Repairs: 154 Gul Circle. 3 Val.: Yes or No Survey held at Lum Sum: Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or CA / REV / REP. / 24 HRS Yehicle: IN / OUT The U/C / Chassis frame / Body Structure affected due to collision. Person Contacted: Date: Action / Instruction Date / Time w/s will Final fig \$13,520.57 confirmed by email (Red 3251.13, 19%) 24/11/21 Days Of Repair: 13 Date/Time, File Pass to? : Preli. Report Survey Fee: Resurvey No. of Trip: 1 : Final Report Transportation: Date/Time, File Return to? Add Fee: : Site Insp (\$ S + RS.__SI 2) 24/11/21-typist : Interview (\$ Photos : Tech. Invs (\$ Repersonnel: Merimen : Weel and (\$ Lunn Sum / LE. E. C. \$13,520.57 TOTAL