



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21009456/Aqy3e2 Date: 22/03/2023	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKV 167G	Veh. Inspected	SLT 3771R	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10011584/JM	Excess (\$)	0.00	
Assign From	FRAULEINE KHOO	Assign Date	08/09/2021	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 520i	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	WBAXG12000DW34198	Colour	BLACK	
Odometer	172954 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R17	PIRELLI	6 mm	
L/H Front Tyre	225/55 R17	PIRELLI	6 mm	
R/H Rear Tyre	225/55 R17	PIRELLI	6 mm	
L/H Rear Tyre	225/55 R17	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/09/2021	Inspection Date	08/09/2021	
Survey held at	ACE AUTOLUTION PTE LTD 13 KAKI BUKIT ROAD 4 #03-29 BARTLEY BIZ CENTRE SINGAPORE 417807			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	