

Your Ref: SNM21D205019/C03/LEWLC

Date: 15th Nov 2021

Our Ref: CS1/CTI21009490/T1uce2

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: GBE 6851X
INSURED VEHICLE: SLF 9243H
ACCIDENT DATE: 04/09/2021**

We thank you for your instruction on 09/09/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GBE 6851X from M/s ARC Surveyors & Adjusters.
- b) Singapore Accident Statement and Police Report of Vehicles GBE 6851X.
- c) Final Repair Bill of GBE 6851X from M/s A L Motorwerkz.
- d) Colour damaged vehicle photographs of GBE 6851X.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: GBE 6851X
Make & Model	: Nissan NV200 1.5 MT ABS Airbag 2WD 6DR E5 W/RC
Year of Registration	: 2016
Chassis Number	: VSKYBAM20Z0120540
Engine Capacity	: 1461 cc

- 2. We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.