

|   |        |      |             |
|---|--------|------|-------------|
| 1 | of 2 ? | 100% | Find   Next |
|---|--------|------|-------------|



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

|                                                                                                                                           |                                                                         |                              |                |  |
|-------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------|------------------------------|----------------|--|
| <b>Affiliated to Federation Internationale Des Experts En Automobile</b>                                                                  |                                                                         |                              |                |  |
| LONPAC INSURANCE BHD                                                                                                                      |                                                                         | Ref: CS3/LPC21007820/T1vf3-1 |                |  |
| 300 BEACH ROAD                                                                                                                            |                                                                         | Date: 09/09/2021             |                |  |
| #17-04/07 THE CONCOURSE SINGAPORE 199555                                                                                                  |                                                                         | Code: LPC2                   |                |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                         |                                                                         |                              |                |  |
| <b>Insured Veh.</b>                                                                                                                       | GBA 9147Y                                                               | <b>Veh. Inspected</b>        | SMF 7389Y      |  |
| <b>Policy No.</b>                                                                                                                         |                                                                         | <b>Coverage (\$)</b>         | 0.00           |  |
| <b>Claim No.</b>                                                                                                                          | 21/21/21/VC00/024787                                                    | <b>Excess (\$)</b>           | 0.00           |  |
| <b>Assign From</b>                                                                                                                        | GERALD POH                                                              | <b>Assign Date</b>           | 09/09/2021     |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                             |                                                                         |                              |                |  |
| <b>Make &amp; Model</b>                                                                                                                   |                                                                         | <b>c.c</b>                   | 0              |  |
| <b>Engine No.</b>                                                                                                                         | HIDDEN                                                                  | <b>Year of Reg.</b>          |                |  |
| <b>Chassis No.</b>                                                                                                                        |                                                                         | <b>Colour</b>                |                |  |
| <b>Odometer</b>                                                                                                                           | -                                                                       | <b>Steering</b>              |                |  |
| <b>Brakes</b>                                                                                                                             |                                                                         | <b>Modification</b>          |                |  |
| <b>General</b>                                                                                                                            |                                                                         |                              |                |  |
| <b>3. Conditions of Tyres</b>                                                                                                             |                                                                         |                              |                |  |
|                                                                                                                                           | <b>Size</b>                                                             | <b>Make</b>                  | <b>Balance</b> |  |
| <b>R/H Front Tyre</b>                                                                                                                     |                                                                         |                              | mm             |  |
| <b>L/H Front Tyre</b>                                                                                                                     |                                                                         |                              | mm             |  |
| <b>R/H Rear Tyre</b>                                                                                                                      |                                                                         |                              | mm             |  |
| <b>L/H Rear Tyre</b>                                                                                                                      |                                                                         |                              | mm             |  |
| <b>4. Description of Damages</b>                                                                                                          |                                                                         |                              |                |  |
|                                                                                                                                           |                                                                         |                              |                |  |
| <b>5. General Information</b>                                                                                                             |                                                                         |                              |                |  |
| <b>Accident Date</b>                                                                                                                      | 17/07/2021                                                              | <b>Inspection Date</b>       | 09/09/2021     |  |
| <b>Survey held at</b>                                                                                                                     | TOPMAX AUTO BODYSHOP<br>BLK 3007 UBI ROAD 1 #01-410<br>SINGAPORE 408701 |                              |                |  |
| <b>5a. Remarks</b>                                                                                                                        |                                                                         |                              |                |  |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                         |                              |                |  |