(08/11/13) wef

ASS. REC. BY: Marcus

REF: CS/SM0210098 75/4vf3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMP 870S

at Workshop m/s 918 Motoring

of

Insured: GBD 2186

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted: Anson 64790918

Veh No: SMP 870S Yr Regn: /

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or GA /

Make: Honda Zit c.c

Colour Grey A/C: Insured / Std / NI / NA

Sp.Reading 72166 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: GK3 3423668

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ~~Inorder / Jammed / Leaked / Burnt~~ or affected

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/55-R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	10/9/21	D.O.I.	13/9/21

Survey held at 15 Kaki Bukit Road

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or O/S frt & n/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	awaiting Estimate.

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: ($)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Survey Fee:

Transportation: ___S + RS, ___SI

Photos

Others

TOTAL