

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Anina-C

Date: 07.09.2021
Time: 10:53:40
Page: 1

CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305485979
REGN NO : SHD3985Y
MILEAGE : 000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 06.08.2019
DATE/TIME IN : 06.09.2021 10:55
ACCIDENT DATE : 05.09.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-0593-G	PANEL ASSY-FRONT DOOR LH#	1	1,797.20	20.00	1,437.76	bt	
0002 04-01-0104-0596-X	PANEL ASSY-REAR DOOR LH#	1	1,789.90	20.00	1,431.92	bt	3587.10
0003 28-01-0103-0003-A	FRT DOOR LOGO SONATA CTPL	1 N	75.00	2.00-	75.00	ur	2869.68
0004 28-01-9999-2023-A	APP LOGO REAR DOOR L/R CT	1 N	80.00	0.20	80.00	ur	SN155

SUB-TOTAL : 3,024.68

3024.68

JOB NATURE

0000 PB	PANEL BEATING
0001 SP	SPRAYPAINT CHARGE
0002 L	TRANSFER DOOR PARTS

700.00	350
600.00	500
240.00	120

970

SUB-TOTAL : 1,540.00

TOTAL : 4,564.68

3994.68

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO

4/5/3200
2 days

Tanpin 97415749
ur 8/11/21 @ 1650
4/5 rtp resurvey before paint
tanpin@khant.com
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: