

ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969

| Our Ref | 3000 | | |
|---------|----------|--|--|
| | 12-09-21 | | |
| Date | : | | |

- AAAAAAA

Via Fax

Time of Fax

Date of Acc

Your Insured

Attn: Motor Claims Department

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH

Our client has engaged us to repair the above vehicle and submit claims against the other party/partiesinvolved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

Our initial estimate of repairs of the damaged vehicle:

ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

◆ Lim Kwok Eng Tel: 6214 8355 or HP: 9824 0811 ◆ Jumani Bin Masudin Tel: 6214 8315 or HP: 9635 5305 ◆ Lim Tien Siong Tel: 6214 8398 or HP: 9635 8546

jumanibm@cdge.com.sg Fax no. 6546 8156

Chiang Liat Choon

Tel: 6214 8314 or HP: 9296 6006

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

For Vice President Taxi Accident Repair



ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops 205 Braddell Road Singapore 579701 59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717

Date/Time: 13.09.2021 16:09

Page: 1

JOB CARD Sales Order: 4118271 ARC Repair TP(CLSO)1 am: JC NO305486689 OMER REGN NO.: SHD4431Y MILEAGE COMFORT TRANSPORTATION PTE LTD MAKE FUEL 7010045 HYUNDAI OMER NO. 383 SIN MING DRIVE E.....F MODEL IONIQ(G3) 13.09.2021 12:00 Singapore SINGAPORE 575717 65508755 (R) YR OF MANU. 19.12.2019 TARGET DATE CHASSIS CODE KMHC851CVLU190345 COMPLETION DATE/TIME: JUNT CARD NO.

JOB DESCRIPTION


:cident Date: 12.09.2021 TURE: 3P.12.09.2021

urned to Service Reception upon collection

NO

LABOR CODE

DESCRIPTION



| | | | EFT SIDE REAR |
|----------------------|----------------|-------------------------|----------------------|
| | | | 1 |
| KED & PASSED OUT BY: | * V | 4 | |
| SERVICE ADVISOR | 20 | | CUSTOMER'S SIGNATURE |
| edgement Slip | | Exit Pass | |
| o.: SHD4431Y | JU AIG | Vehicle No.: SHD4431Y | |
| Service Advisor | Signature/Date | Name of Service Advisor | |

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 13.09.2021 Time: 16:18:22

Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS) JOB NO 305486689 : SHD4431Y **CUSTOMER: 7010045** REGN NO ADDRESS: COMFORT TRANSPORTATION PTE LTD ; 0000000000 MILEAGE

383 SIN MING DRIVE

MAKE : HYUNDAI SINGAPORE SINGAPORE 575717 MODEL : IONIQ(G3)

: 19.12.2019 : 13.09.2021 12:00 65508755 DATE OF REGN

DATE/TIME IN

12.09.2021 ACCIDENT DATE

JOB / PARTS DESCRIPTION

OTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-0578-G COVER-FR BUMPER# 1 430.90 20.00 344.72

0002 04-01-0104-2696-G GRILLE ASSY-RADIATOR# 1 1,598.60 20.00 1,278.88

0003 04-01-0104-2687-G MOULDING-FRONT BUMPER CTR 1 368.50 20.00 294.80

0004 04-01-0104-2935-G LAMP ASSY-HEAD RH# 1 1,993.65 20.00 1,594.92

0005 04-01-0104-3918-G BRACKET-FR BUMPER SIDE RH 1 25.00 20.00 20.00

0006 04-01-0101-0111-G BUMPER COVER CLIP REAR 10 L 22.00 20.00 17.60

SUB-TOTAL : 3,550.92

JOB NATURE

0000 PB PANEL BEATING 400.00

SPRAYPAINT CHARGE 0001 SP 300.00

0002 17-01 CHECK ALL LIGHTING 50.00

SUB-TOTAL : 750.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 13.09.2021 Time: 16:18:22

Page: 2

REPAIR ESTIMATE

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO

305486689

REGN NO MILEAGE : SHD4431Y : 0000000000

MAKE

: HYUNDAI

MODEL : IONIQ(G3)
DATE OF REGN : 19.12.2019
DATE/TIME IN : 13.09.2021 12:0

ACCIDENT DATE : 12.09.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 4,300.92

AUTHORISED: YES/NO SURVEYOR NAME & SIGNATURE

MVA NAME & SIGNATURE

DATE:

DATE:

Enquire Vehicle-Related Transaction History

Transaction History Details

Log Date/Time:

13 Sep 2021 / 15:01:08

Asset Type:

Vehicle

Transaction Amount:

\$7.49

Asset ID:

Transaction Type:

SNB2909P

CORNELIUS

18.32 Insurance Enquiry (GIRO Payment)

Channel:

External Agency

User ID:

ECENGCCO - GOH CHENG CHUAN ANDREWBusiness Transaction

Reference No.:

20210913150108613769

Search Date / Time:

12 Sep 2021 19:40:00

Insurance Company:

AIG ASIA PACIFIC INSURANCE PTE. LTD.

Information displayed is correct as at the log date and time.

Enquire Related Logs

ОК