


ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD/TP/WS/TP RES/OD RES/EVA/INV/MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s: \_\_\_\_\_  
 of: \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: FBR201117 ✓ Yr Regn: 13/3, 2020  
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Private Motor /  
 Truck / Trailer or \_\_\_\_\_ 169  
 Make: Lambretta V200 c.c. 200  
 Colour: black A/C: Insured / Std / Nil / NA  
 Sp. Reading: Not avail. T/Radio: Insured / Std / Nil / NA  
 Eng/No: \_\_\_\_\_  
 C/No: VOLLPB01555002975  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil / VR / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: Ho ~~110~~ 110/70-12  
 R: 170/70-12

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: 10k  
 IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: 4 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % J-Val: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_  
 Front R/Bal. 6 mm Rear R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. 7/9/21 D.O.I. 15/9/21  
 Survey held at equator brotherhood  
 Des. of Damages: Frt / OOD / O/S / MIS / UIC / Roolltop or  
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>GEA in work views</u>
	<u>OE: 4300</u>
	<u>MV: 10k</u>
	<u>Rate: 3651</u>
	<u>NV: 6349</u>
	<u>rr: 2.5h - 3h</u>

SUBMIT PRS REPORT

Date/Time. File Press to?  : Proff. Report  
 : Final Report  
 Date/Time. File Return to? \_\_\_\_\_

Days Of Repair: 4  
 Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  : Site Insp (\$)  
 : Interview (\$)  
 : Tech. Insp (\$)  
 : MVA/ELI (\$)

Survey Fee:	_____
Transportation:	_____
_____ \$ + RS. _____ \$	_____
Photos	_____
Witness	_____
_____	_____
_____	_____

Request Forbid:  
 Date: \_\_\_\_\_

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

#### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 256E

#### Vehicle Details

Vehicle No.: FBR2014D  
Vehicle to be Exported: No  
Intended Deregistration Date: 20 Sep 2021  
Vehicle Make: LAMBRETTA  
Vehicle Model: V200 SPECIAL FLEX CVT ABS  
Primary Colour: Black  
Manufacturing Year: 2018  
Engine No.: XS1P58QMK18006588  
Chassis No.: VDLLPB015JS002975  
Maximum Power Output: -  
Open Market Value: \$2,599.00  
Original Registration Date: 13 Mar 2020  
First Registration Date: 13 Mar 2020  
Transfer Count: 1  
Actual ARF Paid: \$390.00

#### Intended PARF Rebate Details

PARF Eligibility: No  
PARF Eligibility Expiry Date: -  
PARF Rebate Amount: \$0.00

#### Intended COE Rebate Details

COE Expiry Date: 12 Mar 2030  
COE Category: D - Motorcycle  
COE Period(Years): 10  
QP Paid: \$4,310.00  
COE Rebate Amount: \$3,651.00  
Total Rebate Amount: \$3,651.00

The information contained herein is correct as at 20 Sep 2021

OK

$$11280 \div 120 = 94$$

$$8456 / 102$$

$$8456 / 102 = 82.9$$
$$\approx 83$$



Make or Model

Type

Price From

Price To

Class

Any

Any

Any

Any

Search



Share

Share

Report >

6

### Lambretta V200 Special

Brand	Lambretta
Model	Lambretta V200 Special
Engine Capacity	169
Class	2B
Type of Vehicle	Scooters

**SGD \$6980**

Details

On The Road: \$6980 Before COE & Insurance ONLY