

ASS. REC. BY:

REF:

CT2/21009710/Kt

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Soon:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMW1572J

Yr Regn:

04, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

SA : Wagon

Make:

Toy Vel/Are

c.c

2493

Colour

M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

62730

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

AGH30 . 0197416

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

235 / 50R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / Got B2

lump sum 5000, 7days
red: 9917,66%

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

7

Resurvey No. of Trlp:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

S - RS - SI

Fees

Others

TOTAL

Report-Format :

Lump Sum / I.B.I: (\$



GOLD PERFORMANCE PTE LTD

Block 5033 Ang Mo Kio Industrial Park 2 #01-251/259

Singapore 569536

Mobile : 97289234

Email : goldperformancepl@gmail.com

UEN & GST Registration no:202039762K

Not Withheld
1-21, 11/12/2021

15.09.2021

QUOTATION-THIRD PARTY CLAIM

Q:20210902

Pre-Repair Inspection / Assessment

Attention: The Claims Manager
cc: Vehicle Owner - Mr Tay Choon Mong

Email:claimsdept@sg.cntaiping.com

Dear Sir / Mdm

**ESTIMATE REPAIR COST OF SMW1572J (TOYOTA VELLFIRE) on an accident on 13.09.2021
at about 6pm along BuangKok Green towards SengKang**

Item	Description	Qty	Unit Price:S\$	Total:S\$
To supply parts:-				
01	Rear Tailgate / Boots	1 pc	1,260.00	1,260.00
02	Pulling Cap	1 pc	42.00	42.00
03	Rear Tailgate Chrome Panel	1 pc	580.00	580.00
04	Rear "Vellfire" Badge	1 set	75.00	75.00
05	Rear Tailgate Inner Garnish (Cover)	1 pc	620.00	620.00
06	Rear Tailgate Rubber Moulding	1 pc	180.00	180.00
07	Rear WindScreen Assy	1 pc	770.00	770.00
08	Rear WindScreen Gum / Sealant	1 set	44.00	44.00
09	Taillamp Assy	2 pcs	680.00	1,360.00
10	Rear Tailgate Absorber Stand	2 pcs	190.00	380.00
11	Rear Bumper	1 pc	1,224.00	1,224.00
12	Rear Bumper Support Bracket	2 pcs	65.00	130.00
13	Rear Bumper Towing Hook Cover	2 pcs	22.00	44.00
14	Rear Tailgate Lock	1 pc	330.00	330.00
15	Rear Bumper Reverse Sensor	2 pcs	190.00	760.00
16	Rear Bumper Retainer Bracket	2 pcs	85.00	170.00
17	Rear Bumper Clips	10 pcs	2.50	25.00
18	Rubber Stopper for Tailgate	2 pcs	9.00	18.00
19	Rear Panel Garnish	1 pc	155.00	155.00
20	Spare Tyre Compartment (FloorBoard)	1 pc	380.00	380.00
21	Rear Taillamp Panel (Corner)	2 pcs	230.00	460.00
				9,007.00
To supply labour:-				
01	To knock, weld, repair and renew all areas affected by the accident			1,600.00
02	To spray paint all areas affected by the accident			1,800.00



GOLD PERFORMANCE PTE LTD

Block 5033 Ang Mo Kio Industrial Park 2 #01-251/259
Singapore 569536

Mobile : 97289234

Email : goldperformancepl@gmail.com

UEN & GST Registration no:202039762K

15.09.2021

QUOTATION-THIRD PARTY CLAIM Pre-Repair Inspection / Assessment

Q:20210902

Attention: The Claims Manager
cc: Vehicle Owner - Mr Tay Choon Mong

Email:claimsdept@sg.cntaiping.com

Dear Sir / Mdm

**ESTIMATE REPAIR COST OF SMW1572J (TOYOTA VELLFIRE) on an accident on 13.09.2021
at about 6pm along BuangKok Green towards SengKang**

Item	Description	Qty	Unit Price:S\$	Total:S\$
03	To remove and install rear windscreen			1201 150.00
04	Loss of use - car rental for 12 days @ \$180.00	12 days	180.00	2,160.00
				14,717.00

We hope that our quotation will meet with your kind approval.

Thank you.

SK

Steven Ko
97289234

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 14/09/2021 13:08 (SGT)
Date of Accident 13/09/2021 18:00 (SGT)
Exact Location of Accident Singapore
Additional Location Information ALONG BUANGKOK GREEN TOWARDS SENGKANG
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMW1572J
INSURED/POLICYHOLDER
Is company? No
Name Of Registered Owner TAY CHOON MONG
NRIC No S1572597D
Email Address apapl@singnet.com.sg
Mobile Phone No (Phone) +65-81126737
Alternative Phone No +65-81126737

VEHICLE PARTICULARS


Manufacturer Toyota
Model Vellfire
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 2500

INSURANCE COMPANY

Name of Insurance Company NTUC Income Insurance Co-operative Ltd
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 5119665105
Cover Note Number drivo CLASSIC, Accessory

DRIVER

Name of Driver TAY CHOON MONG
NRIC No S1572597D



Vehicle A: SMW1572J

Vehicle B: SMX5831E

ALONG BUANGKOK GREEN TOWARDS SENGKANG

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report No. T 20210914/2029

Declaration

I/We declare the foregoing particulars are true in every respect.

Gianesh (S993561)
Customer Care Executive