



Your Ref: 1977818467SG

Date: 28<sup>th</sup> Jan 2022

Our Ref: CS1/AIG21009729/Nqf3e2

**M/s AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way #09-16

Aig Building

Singapore 079120

(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SKE 877E**

**INSURED VEHICLE: SGU 859X**

**ACCIDENT DATE: 14/09/2021**

We thank you for your instruction on 17/09/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKE 877E from M/s Precise Appraiser Pte Ltd.
- b) Singapore Accident Statement of Vehicles SGU 859X.
- c) Colour damaged vehicle photographs of SKE 877E.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SKE 877E
Make & Model	: Mercedes Benz ML350
Year of Registration	: -
Chassis Number	: WDC1641862A487010
Engine Capacity	: 3500 cc

- 2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.