



# Service Request Details

#### Claim

S1M03H4N

Reference

CS3/ASM21009735/Bqc 🥒

Loss Date

1 September 2021

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

2 Sep 2021 5:55:22 PM

**Request Date** 

17 September 2021

Due Date

17 September 2022

Services

Pre-Repair Survey

## Actions

**Next Step** 

Finish the work

Complete Work



## **Vehicle Information**

Incident Vehicle Registration #

SDV4007S

Make

TPVD Volvo

Model

Xc60

## Service Address

, , ,

## Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD 383 SIN MING DRIVE, 575717, Singapore 65551188

## Claim Handler

TEO Kitty

kitty.teo@axa.com.sg

**Additional Instructions** 

Messages2

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

TYPE

SENT





BODY

Dear Kitty, please be informed that the TP PRS IA  $\ldots$ 

0



TYPE

SENT 17/9/21 11:32 AM

FROM LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT S1M03H4N

BODY Dear Kitty, Thank you for the assignment. Yan

