

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission16/09/2021 14:41 (SGT)Date of Accident15/09/2021 17:15 (SGT)Exact Location of Accident88 Flora Rd, Singapore 507003Additional Location InformationOPEN CARPARK OF EDELWEISS PARKCountry/State of LossSingapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number PA6953R

INSURED/POLICYHOLDER

Is company?YesName Of Registered OwnerCHUN YE TRANSPORTATIONCompany Reg No5XXXX179JEmail AddressA3669J@GMAIL.COMMobile Phone No(Phone) +65-90927679Alternative Phone No(Home) +65-90927679

VEHICLE PARTICULARS

Manufacturer Toyota Model Hiace Variant Exact purpose for which vehicle was being used at time of **Employment** accident Are you claiming under your own insurance policy for repair to No - Claiming third party your vehicle? Vehicle Category Commercial vehicle Transmission Auto 2494

INSURANCE COMPANY

Name of Insurance Company

Type of Coverage

ThirdPartyFireTheft

No
Policy Number

Solution

Fleet Number

ThirdPartyFireTheft

Solution

ThirdPartyFireTheft

Solution

ThirdPartyFireTheft

No

Solution

ThirdPartyFireTheft

ThirdPartyFireTheft

ThirdPartyFire

DRIVER

Name of Driver NG SAY BENG NRIC No SXXXX465J

Date Of Birth 22/12/1953 Occupation Outdoor Date Of Driving Pass 23/10/1976 Driving experience 44 YEARS AND 11 MONTHS Gender Mobile Number (Phone) +65-96221485 Alt. Phone Number Email Address A3669J@GMAIL.COM Address **BLK 485B TAMPINES AVENUE 9** Address complement #11-142 Postcode 521485 Is the driver the policyholder? Nο If No. Relationship of the Driver with the Insured **Employee** Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No PASSENGER 1 Name **AUNTY** Gender Female PASSENGER 2 Name **KID** Gender Male PASSENGER 3 Name **KID** Gender Male PASSENGER 4 Name **KID** Gender Male DETAILS OF POLICE ACTION Was the accident reported to the police? Nο Was notice of intended Prosecution given? No If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	No
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMM6957C
Vehicle Manufacturer	_
Vehicle Model	_
Vehicle Variant	_
Vehicle Colour	_
Vehicle Category	Private car
Name of Driver	_
Contact Number	_
Address	_
Address complement	_
Postcode	-
Insurance Company Name	_
Nature Of Damage	_
Details of property damaged in accident	_
No. Of Passenger (Including Driver)	_

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (ii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signalure / Date &

NS

Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Co. Reg. No 2013186850

Sketch Plan

A = PA 6953R B = 9mm 6957C Open Carpark of

Edelweiss Park

	of the Accide				
					/
					/
				-/-	
	77-115	7.4 E. W.		$\overline{}$	
			/		
			/_		
		Refer to	Altorial		
		110101 10	/		
		/			
		/			
1 - 1 - 1 - 1					
	/	/			
	_/-				
/	/			72 - 52 - 53	
	3.775 - U				
/					
claration					^
e declare the foregoing partic	ujars are true in ev	very respect.		L	
(4) [2]				1	SELVATOR
(\(\frac{\pi}{2}\)		~ 1	100	/ /	Co. Reg. No. 7

On 15.09.2021 at about 17:15 hours at Open Carpark of Edelweiss Park, I was travelling straight at the above mentioned location. When the front vehicle (B) that travelled in front of my vehicle (A) slowed down and stopped, hence I followed suit.

Suddenly, I saw vehicle (B) started to reverse his vehicle (B). I immediately horn to alert the driver of vehicle (B) but unfortunately, vehicle (B) collided onto the front left hand side portion of my vehicle (A).

I wish to state that I have 4 passengers in my vehicle (A).

Vehicle (A): PA 6953R

Vehicle (B): SMM 6957C