

|   |   |          |   |   |        |     |   |             |
|---|---|----------|---|---|--------|-----|---|-------------|
| ⏪ | ⏩ | 1 of 2 ? | ⏪ | ⏩ | 100% ▼ | 📄 ✓ | 🖨 | Find   Next |
|---|---|----------|---|---|--------|-----|---|-------------|



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                            |                                                                                                  |                                              |            |
|----------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------|----------------------------------------------|------------|
| AUTO & GENERAL INSURANCE (S) PL<br>(BUDGET DIRECT INSURANCE)<br>190 CLEMENCEAU AVENUE #03-01<br>SINGAPORE SHOPPING CENTRESINGAPORE<br>239924 |                                                                                                  | Ref: CS/AGI21009750/Btf3<br>Date: 17/09/2021 | Code: AGI  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                            |                                                                                                  |                                              |            |
| Insured Veh.                                                                                                                                 | SMJ 3553U                                                                                        | Veh. Inspected                               | SLQ 102H   |
| Policy No.                                                                                                                                   |                                                                                                  | Coverage (\$)                                | 0.00       |
| Claim No.                                                                                                                                    | C10011727/CD                                                                                     | Excess (\$)                                  | 0.00       |
| Assign From                                                                                                                                  | FRAULEINE KHOO                                                                                   | Assign Date                                  | 17/09/2021 |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                                |                                                                                                  |                                              |            |
| Make & Model                                                                                                                                 |                                                                                                  | c.c                                          | 0          |
| Engine No.                                                                                                                                   | HIDDEN                                                                                           | Year of Reg.                                 |            |
| Chassis No.                                                                                                                                  |                                                                                                  | Colour                                       |            |
| Odometer                                                                                                                                     | -                                                                                                | Steering                                     |            |
| Brakes                                                                                                                                       |                                                                                                  | Modification                                 |            |
| General                                                                                                                                      |                                                                                                  |                                              |            |
| <b>3. Conditions of Tyres</b>                                                                                                                |                                                                                                  |                                              |            |
|                                                                                                                                              | Size                                                                                             | Make                                         | Balance    |
| R/H Front Tyre                                                                                                                               |                                                                                                  |                                              | mm         |
| L/H Front Tyre                                                                                                                               |                                                                                                  |                                              | mm         |
| R/H Rear Tyre                                                                                                                                |                                                                                                  |                                              | mm         |
| L/H Rear Tyre                                                                                                                                |                                                                                                  |                                              | mm         |
| <b>4. Description of Damages</b>                                                                                                             |                                                                                                  |                                              |            |
|                                                                                                                                              |                                                                                                  |                                              |            |
| <b>5. General Information</b>                                                                                                                |                                                                                                  |                                              |            |
| Accident Date                                                                                                                                | 17/09/2021                                                                                       | Inspection Date                              | 23/09/2021 |
| Survey held at                                                                                                                               | BIFROST AUTO PTE LTD<br>8 KAKI BUKIT AVENUE 4<br>#01-49 PREMIER @ KAKI BUKIT<br>SINGAPORE 415875 |                                              |            |
| <b>5a. Remarks</b>                                                                                                                           |                                                                                                  |                                              |            |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.       |                                                                                                  |                                              |            |