

# REPAIR ESTIMATE\*

VEHICLE NO SH8143B  
MAKE REG 19.12.2019  
MODEL : HYUNDAI IONIQ G4

DATE 17/09/21

PIP

		CHIANG /AIG		
Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER			\$430.90
1	FRONT HEADLAMP RH			\$1,993.65
1	FRONT BUMPER GRILLE RH			\$186.90
1	FRONT DAYLIGHT RH			\$642.50
1	FRONT BUMPER BRACKET RH			\$35.00
1	FRONT FENDER RH			\$588.80
1	FRONT FENDER SHIELD RH			\$164.70
1	FRT FENDER EMBLEM			\$26.60
1	FRONT RH WHEEL COVER			\$346.40
10	FRONT BUMPER CLIPS			\$22.00
SUB TOTAL				\$4,437.45
20.00%				\$854.55
DISCOUNTED TOTAL				\$3,418.20
1	FRT FENDER ADVERTISEMENT			\$100.00
				\$100.00
Labour Charge				
Panel Beating				\$640.00
Spray painting				\$800.00
Check Lighting				\$60.00
TOTAL LABOUR				\$1,500.00
ESTIMATE TOTAL				\$5,018.20

?  
/ SCR  
/ SCR  
X SVL  
?  
/ DD  
?  
/ Del Vec  
/ SCR  
MAY ?

NEC

350  
500  
XNN

NAZ LKK  
17/9/2021 1645  
PIP  
3 DAYS  
CHECK ITEM PHOTOS  
BY PAINT PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Date/Time: 17.09.2021 14:08 Page : 1

Team: ARC Repair TP(CLS0)1 JOB CARD Sales Order: JC NO305487340


CUSTOMER	REGN NO.: SH 8143B	MILEAGE
MR/MS	MAKE: HYUNDAI	FUEL
CUSTOMER NO. 7010045	MODEL: IONIQ(G3)	DATE/TIME IN 17.09.2021 11:25
ADDRESS 383 SIN MING DRIVE	YR OF MANU. 19.12.2019	TARGET DATE
Singapore SINGAPORE 575717	CHASSIS CODE KMHC851CVLU189806	COMPLETION DATE/TIME:
65508755		
EL. (R)		
(P)		
DISCOUNT CARD NO.		

JOB DESCRIPTION

Ident Date: 17.09.2021  
NATURE: 3P 17.09.2021

S/NO LABOR CODE DESCRIPTION

TAKE PHOTOGRAPH  
BEFORE / AFTER  
SPRAY PAINTING



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Knowledge Slip

Exit Pass

ne:  
No.: SH 8143B CHIANG  
icle No.:

Vehicle No.: SH 8143B

ne of Service Advisor

Signature/Date

Name of Service Advisor

Date

be returned to Service Reception upon collection

To be kept by Security Guard