



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21009765/Utf3n2	
			Date: 04/10/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PC 7211G	Veh. Inspected	YP 9492Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2102785/THE	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	20/09/2021	
2. Vehicle Particulars & Condition				
Make & Model	ISUZU NPR85 (M)	c.c	2999	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JAANPR85HJ7100187	Colour	WHITE	
Odometer	249825 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/85 R15	YOKOHAMA	6 mm	
L/H Front Tyre	195/85 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	195/85 R15 (D)	YOKOHAMA	6/6 mm	
L/H Rear Tyre	195/85 R15 (D)	YOKOHAMA	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/09/2021	Inspection Date	21/09/2021	
Survey held at	1ST AUTO PRO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	