

PLEASE ARRANGE TO SURVEY
VEHICLE AT 22 TAMPINES ST 92 (S
528876)

Jonathan Lim
CLAIM DEPARTMENT
DID : 66547606
FAX : 66547540

Date : 20/09/2021
To : LKK AUTO CONSULTANTS PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17M1HCVL000057
Vehicle No : GBG-2465-1
Accident Date : 11/09/2021
Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (M)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
<u>Nett Item</u>			
1	FRONT BUMPER / <i>Cut</i>	571.90	
1	FRONT RH BUMPER RETAINER <i>x NN</i>	181.90	
10	FRONT BUMPER CLIP <i>10</i>	50.00	
1	FRONT RH SIDE STEP <i>cut</i>	67.50	
1	FRONT RH MUFLAP <i>cut</i>	105.50	
1	RH "A" PILLAR <i>Repair</i> X		RESTORE
1	FRONT DOOR RH <i>Repair</i> X	1,071.40	
1	FRONT RH FENDER <i>Repair</i> X		RESTORE
1	FRONT RH UPPER ARM <i>?</i> X	377.90	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Date : 20/09/2021

To : LKK AUTO CONSULTANTS PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17MTHCVE000057

Accident Date : 11/09/2021

Vehicle No : GBG-2465-T

Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (M)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	FRONT RH LOWER ARM ?	228.40	
1	FRONT RH ABSORBER /	140.20	
2	FRONT RH ABSORBER RUBBER STOPPER / SAT.	40.00	
1	FRONT RH ABSORBER BRACKET X NR RESTORE		
1	FRONT RH KUNCKLE ARM ?	315.20	
1	FRONT RH WHEEL HUB ?	453.00	
1	FRONT RH WHEEL BEARING / Im	231.00	
1	TIE ROD END RH ?	142.00	
1	TIE ROD RH ?	98.00	
1	FRONT RH ABS SENSOR / OR	397.00	

Date: 10/06/2021

To: **LEK AUTO CONSULTANTS PTE LTD**

ESTIMATION

Attn: Motor Claims Department

FAX:

Company: ETHOZ Group Ltd

500011 SOUTH BRIDGE ROAD SINGAPORE PTE LTD

Certificate No: D17MCHN-VI00007

Accident Date: 11-06-2021

Vehicle No: C8C 2805 Y

Make & Model: NISSAN NV150 PANEL VAN 1.7 DIESEL (COM)

ESTIMATED REPAIR COST DETAILS

Excess: 0.00 Add Excess: 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP
1	FRONT RH DR A/L CALIPER HOUSING <i>cut</i>	67.50	
1	WHITE RIM COVER <i>cut</i>	161.50	
1	FRONT RH TYRE RIMS INCH <i>cut</i>	237.50	
	Sub Total	493.78	
	Discount 10% On Parts	(49.378)	
Special Note Here			
1	COMPANY DEL AI STRUCKER <i>del</i>	20.00	
1	TYRE WHEEL <i>from</i>	200.00	
1	TOWING CHARGES FROM ACCIDENT AREA INTO W. 500.00 <i>- Invoice</i>	150.00	<i>110</i>

Date : 20/09/2021
 To : LKK AUTO CONSULTANTS PTE LTD
 Attn : Motor Claim Department

ESTIMATION

FAX :

Owner : ETHOZ Group Ltd
 : SOMPO INSURANCE SINGAPORE PTE. LTD.
 Certificate No : D17MTHCVE000057 Accident Date : 11/09/2021
 Vehicle No : GBG-2465-T Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (M)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	370.00	
	Labour & Misc		
	LABOUR TO FACILITATE REPAIR	800.00	600.
	TO REMOVE & INSTALL RHF UNDERCARRIAGE PARTS	200.00	150.
	TO REMOVE & INSTALL RHF RIM INCLUDING TYRE BALANCING	20.00	—
	MOUNT VEHICLE ON CHASSIS ALIGNMENT BENCH & RECTIFY CHASSIS TO RECOMMENDED SPECIFICATION	1,800.00	1800 - photo.
	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT	80.00	60.
	TO RESET & RE-PROGRAM WARNING LIGHT ON	120.00	?

Date : 20/09/2021
 To : LKK AUTO CONSULTANTS PTE LTD
 Attn : Motor Claim Department

ESTIMATION

FAX :

Owner : ETHOZ Group Ltd
 SOMPO INSURANCE SINGAPORE PTE. LTD
 Certificate No : D17MTHCVE000057
 Vehicle No : GBG-2465-T

Accident Date : 11/09/2021
 Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (M)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION
	TO APPLY ANTI RUST COATING
	TO SPRAY PAINTING ON AFFECTED AREAS
	Sub Total

REPAIRER AMT (S)	SURVEYOR APP.
80.00	40.
800.00	700.
3900.00	

Remarks:

7-10 Days

SUB TOTAL	8,714.02
GST 7.0 %	609.98
TOTAL	9,324.00

Surveyor's name:

Gene A. Ong - 82880282

Principal's name:

ETHOZ Group Ltd

Survey Date & Time:

21/9/2021

P/P before paint photos.