



Service Request Details

Claim

S1M03I92

Reference

CS3/ASM21009784/Gtc 🥒

Loss Date

17 September 2021

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

20 Sep 2021 10:58:09 AM

Request Date

20 September 2021

Due Date

27 September 2021

Services

Pre-Repair Survey

Actions

Next Step

Agree to perform service

Decline Work



Vehicle Information

Incident Vehicle Registration #

SLL1914B

Make

TPVD Mazda

Model

2

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD 383 SIN MING DRIVE, 575717, Singapore 65551188

Claim Handler

LOH Cynthia

cynthia.loh@axa.com.sg

Additional Instructions

 Messages1
 Invoices
 History
 Documents
 Assessment
 Metrics
 Notes

 New Message

TYPE

SENT 20/9/21 2:28 PM

9/20/21, 2:28 PM VendorEngage



Menu

BODY

Dear Cynthia, Thank you for the assignment. Yan

