

PRS

ASSIGNMENT

From:

Date:

Veh No:

SLL1914B

Yr Regn: 16 Feb 2017

Estimated Cost:

Type ☒ M.Car ☐ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /OD ☒ TP ☐ N/S / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

Make:

MAZDA 2

c.c 1496

at Workshop m/s

REVOL CARZ GARAGE

Colour:

Red

A/C: Insured / Std / NI / NA

of

Sp. Reading

40955

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

MM6DL2SAAGW191471 *

Claims No.

Gen. Cond

☒ Good ☐ Fair / Poor / Burnt

Sum Insured:

Excess:

Steering:

☒ Inorder ☐ Jammed / Leaked / Burnt or

(Client's Record)

Brake:


☒ Inorder ☐ Jammed / Leaked / Burnt or

Make of Veh:

Modi:

Nil / S/Rim / ☒ STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$48k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

☒ BS ☐ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

21-09-2021

Survey held at

W/S

3PM

Des. of Damages: Frt /

☒ Rea

/ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$1500 - \$2500

Date/Time, File Pass to?



: Preli. Report

1)

Date/Time, File Return to?



: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Insp (\$



: W/Weekend (\$

3 + RS. SI

Photos

Other:

TOTAL

Report Filed:

Long Cond / MPB: