

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

DATE: 20-Sep-21

MODEL: Hyundai i40

VEHICLE NO. SHD3036L

INSURANCE: LKK- (L/S)
AIG ASIA

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Bumper	1		\$1,052.20
	Front Bumper Clips	10	\$2.20	\$22.00
	Front Bumper Reinforcement	1		\$588.40
	Radiator Grille	1		\$1,480.00
	Radiator Grille H Emblem	1		\$129.50
	SUB TOTAL			\$3,272.10
	LESS 20%			\$654.42
	DISCOUNTED SPARE PARTS TOTAL			\$2,617.68
	<u>Labour Charge</u>			
	Panel Beating			\$300.00
	Spray Painting Charge			\$300.00
	TOTAL LABOUR			\$600.00
	ESTIMATE TOTAL			\$3,217.68

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

thervan@lkhauto.com
 82235769
 20/9/21 1600
 2 days wp
 L/S after repair photos

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 20.09.2021 10:54 Page : 1

Job: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO 305487613

DMER

S COMFORT TRANSPORTATION PTE LTD
 DMER NO 7010045
 ESS 383 SIN MING DRIVE
 Singapore SINGAPORE 575717
 (R) 65508755 (O)
 (P)


JUNT CARD NO.

REGN NO: SHD3036L	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 20.09.2021 09:30
YR OF MANU. 08.12.2016	TARGET DATE
CHASSIS CODE KMHLB41UMHU096730	COMPLETION DATE/TIME

JOB DESCRIPTION

Accident Date: 16.09.2021
 Accure: 3P 16.09.2021

NO LABOR CODE DESCRIPTION



RECEIVED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Edge Slip

Exit Pass

Job: SHD3036L LIMITS

Vehicle No.: SHD3036L

Service Advisor

Signature/Date

Name of Service Advisor

Date

Turned to Service Reception upon collection

To be kept by Security Guard