

ASS. REC. BY: TGLim

REF:

C5/MSG 21009791 / Buf3

Hui Shen

ASSIGNMENT

From: _____ Date: 21/9/2021

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: JTL 6085

at Workshop m/s MS Cars

of 8 Kaki Bt Aved Premier # 01-07

Insured: 1000994555

Policy No. 262163

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: JTL 6085 Yr Regn: 13/6/2017

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Yamaha LC 135 C.C. 134

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 41504 T/Radio: Insured / Std / NI / NA

Eng/No: G305E - 101298

C/No: PMYU 80810K.010278

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 70/90/17 PIR

R: 80/90/17 MAXIS

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front: _____ Rear: _____

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. / mm L/Bal. / mm

D.O.A. 4/9/2021 D.O.I. 21/9/2021

Survey held at MS Cars

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Recommended cor is LS \$ 2,300/2 TGLim

21/10/2021 Submit preli report - owner withdrawn claim

Not able to check MV and NV

TGLim

21/10/2021

Date/Time, File Pass to?



Preli. Report

1) 21/10 TYPIST



Final Report

Date/Time, File Return to?

2)

Report Format: TP

Lump Sum / L.S. / C.S.

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Hui Zhen
M510

SJE :

Vehicle Nos : JTL 6085

Date of Survey :

ReSurvey:

Model : Yamaha LC135

Contacts :

Year :

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day: 0

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Headlamp cowling BR✓	1	\$ 171.00	\$ 115.00 171.00
2	Headlamp CUT✓	1	\$ 542.00	\$ 285.00 542.00
3	Front cowling BR✓	1	\$ 183.00	\$ ✓ 183.00
4	Front emblem NEG✓	1	\$ 36.00	\$ ✓ 36.00
5	Front fender CUT✓	1	\$ 152.00	\$ ✓ 152.00
6	Fork assy CUT✓	1	\$ 693.00	\$ ✓ 693.00
7	Fork stem NDX	1	\$ 132.00	\$ 132.00
8	Mirror L+R CUT + BR ✓	2	\$ 44.00	\$ ✓ 88.00
9	Handle bar NDX	1	\$ 165.00	\$ 165.00
10	Handle bar balancer CUT✓	1	\$ 46.00	\$ ✓ 46.00
11	Brake lever CUT✓	1	\$ 62.00	\$ 32.00 62.00
12	Front Side cowling L+R DL✓	2	\$ 186.00	\$ ✓ 372.00
13	Brake pedal NDX	1	\$ 45.00	\$ 45.00
14	Clutch pedal NSX	1	\$ 45.00	\$ 45.00
15	Foor rest bar NDX	1	\$ 72.00	\$ 72.00
16	Rear foot rest RH CUT✓	1	\$ 45.00	\$ ✓ 45.00
17	Exhaust assy NDX	1	\$ 788.00	\$ 788.00
18	Exhaust cover CUT✓	1	\$ 86.00	\$ ✓ 86.00
19	Rear side cover RH NDX	1	\$ 136.00	\$ 136.00
20	Rear fenter CUT✓	1	\$ 158.20	\$ 158.20
21	Front signa R/L H NDX	1	\$ 75.20	\$ 75.20
22	Rear signa R/L H NDX	1	\$ 75.20	\$ 75.20
23	Rear side cover NDX	1	\$ 132.60	\$ 132.60
24	Tail lamp NDX	1	\$ 178.50	\$ 178.50
25	Exhaust gasket NNX	1	\$ 72.00	\$ 72.00

Parts Sub Total : \$ 2291.20 4,550.70

Discount 10% : \$ 229.12 455.07

PARTS TOTAL : \$ 2062.08 4,095.63

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Steering cone bearing NNX	1	\$ 116.40	\$ 116.40
2	Centre basket NDX	1	\$ 76.70	\$ 76.70
3	Tail box CUT✓	1	\$ 280.00	\$ ✓ 280.00
4	Front number plate CUT✓	1	\$ 25.00	\$ 25.00
5	Front rim NDX	1	\$ 165.00	\$ 165.00
6	Front Taye NDX	1	\$ 112.50	\$ 112.50
7	Rear box bracker NDX	1	\$ 137.60	\$ 137.60
8	Rear Number plate BT✓	1	\$ 25.00	\$ 25.00
			\$ 3.00	\$ 330.00 938.20

Nos.	LABOUR - FRONT	S\$
1	To R&R accident damage parts, to cut/weld,knock and realign accident affected area	\$ 300.00 500.00
2	Spry pain	\$ 200.00 400.00
3	Front rim alignment NNX	\$ 150.00
4	Conduct chassis alignment NNX	\$ 100.00
5	Body frame alignment NNX	\$ 200.00
LABOUR FRONT TOTAL :		\$ 500.00 1,350.00

PARTS TOTAL :	\$	4,095.63
SPECIAL NETT TOTAL :	\$	938.20
LABOUR TOTAL :	\$	650.00
OVERALL TOTAL :	\$	<u>5,683.83</u>

Survey
21/9/2021
1318 hrs
TGM in Min

No resurvey done
claims withdrawn
21/10/2021

Lump sum repair
Repair days 4

Parts	2 062.08
SN	330.00
Labour	<u>500.00</u>
	2892.08
@ 20%	<u>578.42</u>
	2313.66

L/S 2,300/r

TGM in Min
21/10/2021

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



**SINGAPORE
POLICE FORCE**



T/20210905/2041

1 of 3

Police Station Of Origin:
Chai Chee NPP
35 Chai Chee Avenue #01-256 SINGAPORE
461035
Tel No: 1800-4459999

Report No. T/20210905/2041

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 05/09/2021 13:56	Vide Report No.: G/20210904/0259	Station Diary No.: 10
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: WONG WEI LIONG			Address: APT BLK 56 CHAI CHEE DRIVE #04-142 SINGAPORE 460056		
ID Type / ID No.: FIN NO / G2956430U			Contact No.: Home/Office: Mobile: 94463660		
Nationality: MALAYSIAN			Email: wong8886085@gmail.com		
Sex: Male	Age: 27	Date of Birth: 05/08/1994	Type of Informant: Rider		
Race: Chinese			Language:		Institution / School Name:
Occupation: WAREHOUSE ASSISTANT			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 04/09/2021 19:10	Type of Location: Straight Road
Location: BEDOK RESERVOIR ROAD				
Weather: Raining		Road Surface: Wet		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled		Traffic Volume:
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
JTL6085	Motorcycle				Slightly Damaged	1
SGV5953T	Car				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL	



**SINGAPORE
POLICE FORCE**



T/20210905/2041

Police Station of Origin:
Chai Chee NPP
35 Chai Chee Avenue #01-256 SINGAPORE
461035
Tel No: 1800-4459999

2 of 3

Report No: T/20210905/2041

CONTINUATION OF REPORT

Rider			
Name	WONG WEI LIONG	ID No.	G2956430U
Related Vehicle	JTL6085 (Motorcycle)	Contact No.	94463660
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	04/09/2021	Date Discharge	04/09/2021
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Pillion			
Name	TEE KOK YUEN	ID No.	G2794206M
Related Vehicle	JTL6085 (Motorcycle)	Contact No.	88985894
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	04/09/2021	Date Discharge	04/09/2021
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On 04/09/2021 at about 1910 hrs, I was riding on my motorcycle JTL6085 along Bedok Reservoir Road towards Jalan Damai on the left lane of the 2 lanes road with my friend whom is my pillion. Then, there was a car SGV5953T which was in front of me signaling to the left. I slowed down and subsequently, the car signaled to the right. When we reached outside the Alkaff mosque, the car had moved slightly to the right which I assumed that the driver will be changing his lane to the right lane. Then out of a sudden, the car turned to the left and entered the mosque without any signal. I could not stopped in time and collided to the rear left of the car.

I wished to state that both me and my pillion were conveyed to Changi General Hospital and both of us were given 3 days of medical leave. I suffered some abrasions on my right hand and leg and I felt some pain on my nose. My pillion suffered abrasions on his right hand and leg too. My motorcycle sustained slight damages to the front portion. I am lodging this report with reference to G/20210904/0259.



**SINGAPORE
POLICE FORCE**



T/20210905/2041 ✓

3 of 3

Police Station Of Origin:
Chai Chee NPP
35 Chai Chee Avenue #01-256 SINGAPORE
461035
Tel No: 1800-4459999

Report No. T/20210905/2041 ✓

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature of Officer Recording The Report
G /
Sr Staff Sgt MUHAMMAD
KAMARULARIFIN BIN
MOHAMED YUSOFF


Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / AEIT /
Sr Staff Sgt SYED ZAYID MUHAMMAD BIN
SYED ABDUL WAHID ALHINDUAN
Contact No.: 65476404

Signature Of Informant:

Date/Time:
05/09/2021 13:56

Classification Of Case:



SIGNATURE



DAFTAR PENDAFTARAN

DAFTAR PENDAFTARAN

No. Pendaftaran	JFL0005
No. Urut	0000010050
Nama/Pada Nama	BONG HUI LING
Alamat	NO 57 TIRI SRI KESANG PT BUNGA KESANG 34003 BUAN JOROR
No. Chassis/No. Enjin	PSYU80310K0101279 / 0385E-101296
Badan/Mama Model	YAMAHA / YAMAHA 135LC
Kemungkinan Enjin	134
Bahan Bakar	PETROL
Status Asal	PENASANGAN TEMPATAN
Kelas Kategorisasi	MOTOSIKAL
Jenis Badan/Tahun Dibuat	MOTOSIKAL / 2019
Tarikh Pendaftaran	13/06/2019
O.D. B/S. G. K/SIR	-
Status Pendaftaran	-
Spesifikasi	-
Spesifikasi	-

CERTIFICATE OF INSURANCE

ROAD TRANSPORT ACT, 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD PARTY RISKS, RULES 1989 (MALAYSIA)
THE MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT
CAP 189 (REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES 1980 (REPUBLIC OF
SINGAPORE)
THE MOTOR VEHICLES INSURANCE (THIRD PARTY RISKS) ACT (CAP 90) NEGARA BRUNEI DARUSSALAM

SIJIL INSURANS

AKTA PENGANGKUTAN JALAN RAYA, 1987 (MALAYSIA)
PERATURAN KENDERAAN MOTOR (RISIKO PIHAK KETIGA) 1989 (MALAYSIA)
AKTA KENDERAAN MOTOR (RISIKO DAN PAMPASAN PIHAK KETIGA) (CAP 189) (REPUBLIK SINGAPURA)
PERATURAN KENDERAAN MOTOR (RISIKO DAN PAMPASAN PIHAK KETIGA) 1980 (REPUBLIK
SINGAPURA)
AKTA INSURANS KENDERAAN MOTOR (RISIKO PIHAK KETIGA) (CAP 90) NEGARA BRUNEI
DARUSSALAM

Certificate No. (No. Sijil) : 501900099109-02

D13970-000

1. Index Mark and Registration Number of Vehicle : JTL6085
(Tanda Indeks dan Nombor Pendaftaran Kenderaan) : YAMAHA 135 LC
2. Name of Policyholder (Nama Pemegang Polisi) : WONG WEI LIONG
3. Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance of
Enactment : 13 JUN 2021
4. Date of Expiry of the Insurance (Tarikh Insurans Tamat) : 12 JUN 2022
5. Persons or Classes of Persons entitled to drive* (Orang atau Kelas Orang yang berhak memandu*):

NCD : 20.00 %

a) Policyholder b) Any other person who is riding on the Policyholder's order or with his permission. Provided that the person riding is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from riding the Motorcycle.

Limitation on Usage

Use for social domestic and pleasure purposes and by the Policyholder in person in connection with his business or profession. The policy does not cover :- Use for hire or reward, racing, pace-making, reliability trial, speed- testing or the carriage of goods (other than samples) in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 95 of the Road Transport Act 1987 (Malaysia) or Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore or Section 7 of the Motor Vehicles Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam are not to be included under these heading.

* Had - had yang tidak lagi berkuatkuasa kerana Seksyen 95 Akta Pengangkutan Jalan Raya, 1987 (Malaysia) atau Seksyen 8 Akta Kenderaan Motor (Risiko Dan Pampasan Pihak Ketiga) (Cap 189) Republik Singapura atau Seksyen 7 Akta Insurans Kenderaan Motor (Risiko Pihak Ketiga) (Cap 90) Negara Brunei Darussalam tidak boleh dimasukkan di bawah tajuk ini.

Insured in pursuance to cover Note No : D13970-21001844

Dikeluarkan mengikut Nota Lindungan No :

I / We hereby certify that the Policy to which the Certificate is issued in accordance with the provisions of Part IV of the Road Transport Act, 1987 (Malaysia), Motor Vehicles (Third Party Risks & Compensation) Act (Cap 189) Republic of Singapore and the Motor Vehicles Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam.

Saya / Kami dengan ini mengesahkan bahawa Polisi yang berkaitan dengan Sijil ini dikeluarkan selaras dengan peruntukan - peruntukan Bahagian IV Akta Pengangkutan Jalan Raya, 1987 (Malaysia), Akta Kenderaan Motor (Risiko Dan Pampasan Pihak Ketiga) (Cap 189) Republik Singapura dan Akta Insurans Kenderaan Motor (Risiko Pihak Ketiga) (Cap 90) Negara Brunei Darussalam

For and on behalf of / Untuk dan bagi pihak
ZURICH GENERAL INSURANCE MALAYSIA BERHAD



Junior Cho
Chief Executive Officer