ASS. REC. BY: MC. 165	1009800/Uuf3
	GNMENT
2	Veh No: SIN 8751/ Yr Regn: 19/5/17
From: Date: Estimated Cost:	Type/M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
(6) TP/WS/TP RES/OD RES/EVA/INV/MV	Truck/Trailer or A/1.57urbo
To Inspect Vehicle No: 51 N 675/4	Make: Hunder Civic c.c 1498
at Workshop m/s AIM	Colour Suc A/C: Insured / Std / NI / NA
of	Sp.Reading 37.5-64 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No. MPC21P00182900	C/NO: MRH FC/660HT000070
Claims No. DMPC2100324H	Gen. Cond: good / Fair / Poor / Burnt
Sum Insured: Excess: O	Steering: Ingreer / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Incorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil SARim / STD A/Rim or
	Tyre Size: F: 235-/402R/8
(Policy Condition)	R:
Remark: The veh had commenced its	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO OF habilead
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. / mm R/Bal. / mm
GIA / PR Seen: Consistent? : Yes or No	(10/01)
Est. Repairs:	10(1)
Lum Sum: 23 % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS OF /// Vehicle: IN / OUT	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or N/S Rear & Pr/O/S. Rear
Date: Person Contacted: 773/h	The Ulc I Chassis frame I Body Structure affected due to collision.
Date / Time Action / Instruction	
revert P/P Become NO Seend cost plus. LJAC 48914	hard garls
cost plus. LTAC 48914	
10/1 4/5 \$ 9200 confirmed.	wh (lelvin 12 repair days
(RED \$17597.10; 66%)	
(1425 \$17001.10, 0070)	
Date/Time, File Pass to? Preli. Report	Days Of Repair: 12
1) 11/10 TYPIST : Final Report Date/Time, File Return to?	Resurvey No. of Trip: 2 Survey Fee: Transportation:
Add Fee:	: Site Insp (\$)S+RSSI
•	: Interview (\$) Photos
Report Format: MER-OD	: Tech. Invs (\$) Others
Lump Sum / 1.B.1. (\$ 9200)	: Weekend (\$)
	TOTAL

Automobile Integrated Management Pte Ltd

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Email Address: automim.claim@gmail.com

Reg: 201605297G

Vehicle Number : Vehicle Model:

SLN8751Y

Chassis:

HONDA CIVIC

MRHFC1660HT00007

Accident Date: 16.09.2021 Original Reg Date: 19.05.2017

OD Ins.

ECICS Ltd 1/2 \$9200

			_			
		<u>ESTIMATE</u>		•	507.00	12
1	1	FRT SUPORT PANEL ASSY	cne	\$	507.00	
2	1	FRT WHEELHOUSE MEMBER RH	1	\$	72.00	3
3	1	FRT WHEELHOUSE EXTENSION RH		\$	169.00	×
4	1	FRT FENDER RH	BNC	\$	208.00	
5	1	FRT FENDER BRACKET RH	cre	\$	33.00	
6	1	FRT FENDER ENCLOSURE RH	11	\$	13.00	X
7	1	FRT FENDER INNERSHIELD RH	TILA	\$	59.00	
8	1	FRT BONNET	r	\$	520.00	人
9	1	RR CHASSIS PANEL LH	7	\$	494.00	X
10	1	RR SPARE TYRE PANEL EXTENSIO	NLH /	\$	46.00	X
11	1	RR END PANEL	5	\$		X
12	1	RR END PANEL STIFFENER LH	R.	\$	26.00	×
13	1	RR TAILLAMP PANEL LH	D/14	\$	59.00	-
14	1	RR FENDER GUTTER PANEL LH	Repla	\$	46.00	X
15	1	RR FENDER LH	アノ	\$	624.00	-
16	1	RR FENDER AIR DUCT LH	CN	\$	11.00	2
17	1	RR FUEL FILLER COVER	3mt	\$	98.00	
18	1	RR FUEL FILLER COVER LOCK ACT		\$	85.00	
19	1	RR FUEL FILLER ADAPTER	CM	\$	50.00	x
20	1	RR FUEL FILLER CAP		\$	59.00	
21	1	RR FUEL TANK ASSY	11	\$	650.00	X
22	1	RR WINDSCREEN	11	\$	455.00	Y_
23	1	RR WINSCREEN MOULDING	nn	\$	33.00	
24	3	RR WINDSCREEN INNER SEAL	m	\$	78.00	X
25	1	RR QUARTER GLASS ASSY LH	11	\$	130.00	^
26	1	RR DOOR LH	رخ	\$	624.00	
27	1	RREDGOR WEATHERSTRIP LH	ner	\$	72.00	
28	1	RR DOOR LOW SEAL LH	nn	\$	10.00	,
29	1	RR DOOR HINGE UPP LH	11	\$	39.00	X
30	1	RR DOOR HINGE LOW LH	11	\$	39.00	بخرا
31	1	RR DOOR CHECKER LH	11	\$	20.00	×
32	1	RR DOOR STOPED	11	\$	7.00	×
33	1	RR BOOTLID	11	\$	390.00	X
34	1	RR BOOTLID TOP SPOILER	٨٨	\$	1,300.00	_ ×
35	1	RR BOOTLID OUTER GARNISH	11	\$	98.00	X
36	1	RR BOOTLID LOCK	^1	\$	72.00	以.
37	1	RR BOOTLID LOCK CATCHER	^ ^	\$	8.00	X

,	V-	•			
38	.: 1	RR BOOTLID WEATHERSTRIP	17	\$ 46.00	X
.39	1	RR BOOTLID STOPED	17	\$ 6.00	父
40	1	RR BOOTLID STOPED LOW	11	\$ 13.00	又
41	1	RR BOOTLID DRAIN PLUG	17	\$ 4.00	人
42	1	RR DOOR INNER TRIM BOARD LH	11	\$ 671.00	
43	1	RR FENDER INNER TRIM LH	ae	\$ 52.00	
44	1	RR BOOTLID LOGO	11	\$ 13.00	
45	1	RR BOOTLID VTEC TURBO EMBLEM		\$ 26.00	`
46	1	RR BOOTLID CIVIC EMBLEM	10	\$ 13.00	
47	1	RR FUEL FILLER CAUTION STICKER		\$ 8.00	
48	1	RR DOOR BLACK STICKER LH(frt)	nu	\$ 26.00	
49	1	RR DOOR BLACK STICKER LH(rr)	ner	\$ 26.00	
50	1	RR DOOR OUTER MLDG LH		\$ 52.00	×
51	1	RR DOOR OUTER UPP MLDG LH	17	\$ 65.00	メ メ
52	1	RR FENDER INNERSHIELD LH		\$ 59.00	-
53	1	LH ROCKER PANEL GARNISH LH	100	\$ 117.00	
54	1	FRT GRILLE BASE	sin	\$ 91.00	1
55		FRT GRILLE LOGO		\$ 20.00	a
56	1	FRT GRILLE LOGO	17	\$	2
	1		11	\$	4
57	1	FRT GRILLE CHROME MLDG RH	SAR	\$ 26.00	X
58	1	FRT GRILLE TOP SEAL	11	\$ 299.00	-
59	1	FRT BUMPER	Dis	\$ 12.00	
60	1	FRT BUMPER RETAINER RH	cm	\$ 26.00	
61	1	FRT BUMPER BRACKET RH FRT BUMPER TOP CENTRE RETAINE	3 <i>M</i> ER 17	\$ 143.00	X
62	1		9D	\$ 299.00	*-
63	1	FRT BUMPER REINFORCEMENT		\$ 20.00	12
64	1	FRT BUMPER FOG LAMP COVER RH FRT BUMPER LOW CENTRE GRILLE		\$ 72.00	X
65	1			\$ 338.00	
66	1	RR BUMPER	DIS	\$ 39.00	
67	1	RR BUMPER LOW	en en	\$ 16.00	5
68	1	RR BUMPER SIDE RETAINER LH	-	\$ 7.00	
69	1	RR BUMPER BRACKET LH	cn	\$ 13.00	-
70	1	RR BUMPER GARNISH LH	son	\$ 11.00	x
71	1	RR BUMPER REFLECTOR LH	11	\$ 13.00	
72	1	RR BUMPER FINISHER LH	Dis	\$	X
73	1	RR BUMPER REINFORCEMENT	11	.00.00	
74	1	FRT HEADLAMP RH	ena	1,014.00	
75	1	FRT SIGNAL LAMP RH	(12	\$ 33.00	7
76	1	FRT FOG LAMP RH	Che	\$ 208.00	
77	1	RR TAILLAMP LH	300	\$ 221.00	
78	1	RR BOOTLID LAMP LH	11	\$ 98.00	XX
79	1	FRT WIPER WASHER TANK	11	\$ 33.00	*
80	1	FRT WIPER WASHER PUMP	11	\$ 39.00	5
81	1	FRT WIPER WASHER TANK NECK	1.0	\$ 16.00	X
82	1	FRT WHEEL BEARING RH	n1	\$ 98.00	X
83	1	FRT WHEEL BEARING HUB RH	11	\$ 	1
84	1	FRT KNUCKLE RH	11	\$ 163.00	Ž,
85	1	FRT LOW ARM RH	17	\$ 208.00	1

4		1				_
86	: 1°	FRT LOW ARM BALLJOINT RH	11	\$	59.00	X.
,87	1	FRT STABLIZER LINK RH	11	\$	46.00	JX
88	1	FRT ABS SENSOR RH	17	\$	85.00	×
89	1	FRT SHOCK ABSORBER RH	11	\$	260.00]×
90	1	FRT SHOCK ABSORBER TOP MOU	NTING RH 1	7\$	39.00	X
91	1	FRT TIE ROD RH	11	\$	46.00	X
92	1	FRT STEERING RACK END RH	11	\$	39.00	×
93	1	RR WHEEL BEARING LH	Doyer	\$	176.00	
94	1	RR KNUCKLE LH	suf	\$	169.00	>
95	1	RR LOW ARM 1 LH	SU	\$	72.00	7
96	1	RR LOW ARM 2 LH	ser	\$	52.00	1
97	1	RR UPP ARM LH	M	\$	169.00	7
98	1	RR TRAILING ARM LH	Bul	\$	72.00	-
99	1	RR STABLIZER LINK LH	11	\$	39.00	
100	1	RR ABS SENSOR LH	11	\$	65.00	×/
101	1	RR SHOCK ABSORBER LH	1~1	\$	182.00	
102	1	RR SHOCK ABSORBER TOP MOUN	TING LH 1	7 \$	104.00	X

\$ 14,341.00 6302 \$ 1,434.10 \$ 15,775.10 Cost +10%

		Special Nett					7
1	10	FRT BUMPER	R CLIP		NM	\$ 50.00	30
2	10	FRT GRILLE	CLIP		NA	\$ 50.00	_ X
3	6	FRT SUPORT	GARNISH	CLIP	11	\$ 30.00	X
4	10	FRT FENDER	INNERSH	ILED CLIP	NU	\$ 50.00	30
5	1	FRT RIM RH			11	\$ 500.00	X
6	1	FRT TYRE RI	1		11	\$ 300.00] \
7	1	RR RIM LH			11	\$ 500.00	\ \
8	1	RR TYRE LH			SXVC	\$ 300.00	X
9	10	RR BUMPER	CLIP		ne	\$ 50.00	30
10	10	RR FENDER I	NNERSHIE	ELD CLIP	11	\$ 50.00	X
11	_	RR FENDER I			11	\$ 30.00	X
12	6	RR END PANE	EL TOP GA	ARNISH CLIP	17	\$ 30.00	7
13	6	RR BOOTLID	INSULATO	R CLIP	11	\$ 30.00	×
14	1	RR WINDSCR	EEN SEAL	ANT	NN	\$ 60.00	40
15	1	RR WINDSCR	EEN SOLA	AR FILM	11	\$ 200.00	人
16		RR QUARTER			nu	\$ 60.00	30
17		RR QUARTER			11	\$ 100.00	X

FRT Labour charge

- TT Babbar onargo		-
To dismantle / renew the accident damaged portion,to panel beating,reshape,straighten,orientate and align repair /replacement parts.	\$ 1,000.00	500
Carry out spray painting on affected area,FRT BONNET, FRT BUMPER, FRT FENDER RH, PRT-DOOR RH, Suppol	\$ 1,000.00	600
To conduct anti rust of under carriage tuff coat	\$ 1 80.00	X
To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 80.00	20
To remove and replace RHF under carriage parts	\$ 1~300.00	80
To conduct 4 wheel alignment	\$ 120.00	80
To conduct reset of engine light on	\$ 1/2 300.00	乂
To refocus headlamp And	\$ 80.00	X

RR Labour charge

THE BUDGET OFFICE OF THE PERSON OF THE PERSO		-
To dismantle / renew the accident damaged portion,to panel beating,reshape,straighten,orientate and align repair /replacement parts.	\$ 1,600.00	1200
Carry out spray painting on affected area,RR BOOTLID, RR BUMPER, RR END PANEL, RR FENDER LH, RR DOOR LH, LH ROCKER PANEL	\$ 1,600.00	1000
To conduct anti rust of under carriage tuff coat	\$ 17 80.00	X
To disconnect wire harness of electrical component to facilitate repairs,reconnect and check electrical function after repair Remove and refix seat cushion/upholstery & roof lining to	\$ 80.00	20
facilitate repairs	\$ 300.00	R
To remove and refix reverse sensor and conduct test	\$ 80.00	
To remove and refix reverse camera and conduct test	\$ n 180.00	40
To conduct transfer of parts from old bootlid to new bootlid	\$ 1 120.00	X
To conduct water leakage test after repairs of vehicle	\$ ィハ 30.00	V
To apply door sealant to door	\$ 60.00	_
Remove and replace LHR under carriage parts	\$ 300.00	2150
To remove and refit fuel tank to failitate accident repair	\$ 200.00	60
To remove and refit rear windscreen due to replacement of rear		
fender	\$ 180.00	120
To remove and refix rear quarter glass	\$ 120.00	60

LKK	Auto Consultants hence notify
the	Repairer of the following:
• To	resurvey before/after spray painting
• To	display damaged part(s) during resurvey
• Pa	rts prices are subject to confirmation
• Th	ird party survey is on a "Without Prejudice" basis
• No	illegal modification(s) is allowed
• Su is s	pplementary item(s) must be resurveyed <u>and</u> subject to final approval from Insurance Compan
Ackr	nowledged by Repairer
Sign	ature:
Date	

Total	_\$	25,955.10 + \$842
		= \$26797.10
GST 7%	\$	1,816.86
Grand Total	\$	27,771.96 P-6694 102 P-7367.40 18/3,40 SN-160 974,0 1-3990 974,0

SUPPLEMENTARY VEHICLE NO: SLN 875 (Y

		PRICE
QTY	PARTS DESCRIPTION	137
	Firt SRS Crash Sensor RH Doned	
	RR Exhaust silencer box LH X	450
1	RR Taillamp Clip nu	12
-1	RR Bunper Reyerse Sersor one	128
1	RR Bumper Reverse Sersor WIRE hagness and	115
		1
	тф	TAL \$842
4		
	3	
_	* * * * * * * * * * * * * * * * * * * *	
		The second second
		-
		distribution
		The state of the s
		. <u>A</u> .
		T V GP-1
		40
	V	
	(RED \$17597.10; 66	
	\$ 1 m	

META MECHANIC 25 KAKI BUKIT ROAD 4 # 06-66 SYNERGY @ KAKI BUKIT

SINGAPORE 417800 TEL: 98250505

rk Order:

1:

R005128

SLN8751Y hnician:

23.9.21 9:40



Honda : Civic : 2016- (FC/FK) : except Si, Type-R : Type A ExpressAlign Total Alignment

Front: Left

Actual	Before	Specified Range
0°28'	0°28'	-0°48' 0°12'
5°18'	5°18'	4°48' 5°48'
-0°27'	-0°27'	-0°05' 0°05'
-0°28'	-0°28'	and the second
0°00'	0°00'	

Camber Caster Toe SAI

Included Angle Turning Angle Diff. Front : Right

Actual	Before	Specified Range
0°14'	0°14'	-0°48' 0°12'
5°18'	5°18'	4°48' 5°48'
-0°03'	-0°03'	-0°05' 0°05'
-0°14'	-0°14'	
0°00'	0°00'	

Front

Cross Camber Cross Caster Cross SAI **Total Toe** Cross Turn Diff.

Actual	Before	Specified Range
0°14'	0°14'	-0°45' 0°45'
0°00'	0°00'	
-0°14'	-0°14'	
-0°31'	-0°31'	-0°09' 0°09'
-0 31	70 31	-0 03 0 03

Rear: Left

ſ	Actual	Before	Specified Range
	0°43'	0°43'	-1°57' -0°27'
	0°39'	0°39'	0°02' 0°09'

Camber Toe

Rear : Right		
Actual	Before	Specified Range
-0°23'	-0°23'	-1°57' -0°27'
0°08'	0°08'	0°02' 0°09'

Rear

Cross Camber **Total Toe Thrust Angle**

	· · · · · ·			
r	Actual	Before	Specified Range	
ľ	1°06'	1°06'	-0°45' 0°45'	
ſ	0°47'	0°47'	0°05' 0°19'	
ľ	0°15'	0°15'		


> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC	
Owner ID:	773H	
《新型》。1980年,1980年, 1980年, 1980年	n 一个方面是一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个	No.
Vehicle No.:	SLN8751Y	
Vehicle to be Exported:	No	
ntended Deregistration Date:	18 Sep 2021	
Vehicle Make:	HONDA	
Vehicle Model:	CIVIC 1.5 TURBO VTIS SR	
Primary Colour:	Blue	
Manufacturing Year:	2017	
Engine No.:	L15B72451259	
Chassis No.:	MRHFC1660HT000070	
Maximum Power Output:	127.0 kW (170 bhp)	
Open Market Value:	\$27,106.00	
Original Registration Date:	19 May 2017	
First Registration Date:	19 May 2017	
Transfer Count:	1	
Actual ARF Paid:	\$24,949.00 12474	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	18 May 2027	
PARF Rebate Amount:	\$18,711.00	
COE Expiry Date:	18 May 2027	
COE Category:	B - Car above 1600cc or 97kW (130bhp)	
COE Period(Years):	10	
QP Paid:	\$53,300.00	
COE Rebate Amount:	\$30,203.00	
Total Rebate Amount:	\$48,914.00	

ОК

(RED \$



SA0M219H0001 / Automobile Integrated Management Pte Ltd ENTRY DATE & TIME: -SUBMITTED BY: [To Be Confirmed] VERSION: 1 (17/09/2021 16:34 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process
- 2. This Form must be completed by the <u>Policyholder and/or the Authorised Driver</u>
 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate
 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

- 3. Intomator province mass to established to the policy liability.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving
- and that copies of this report will, for a fee, be made available upon application by interested parties. 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Date of Accident

Exact Location of Accident Additional Location Information

Country/State of Loss

16/09/2021 14:45 (SGT) 14 Lornie Rd, Singapore 298700 ALONG PIE TOWARDS CHANGI (BEFORE LORNIE ROAD EXIT

20B) Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SLN8751Y

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner NRIC No

Email Address

Mobile Phone No

Alternative Phone No

TAN MIN PIN ADRIAN

SXXXX773H

automim.ops@gmail.com (Phone) +65-90301090

CIVIC 1.5 TURBO VTIS SR

+65-90301090

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of

accident

Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category

Transmission

(RED \$

CC

Yes Private car

Private use

Honda

Civic

Auto 1498

INSURANCE COMPANY

Name of Insurance Company

Type of Coverage Fleet Policy

Policy Number

Cover Note Number

ECICS Limited Comprehensive No

MPC21P00182900

DRIVER

Name of Driver

TAN MIN PIN ADRIAN

(Draft) NRIC No SXXXX773H Date Of Birth 30/10/1990 Occupation Indoor Date Of Driving Pass 27/07/2012 Driving experience 9 YEARS AND 2 MONTHS Gender Mobile Number (Phone) +65-90301090 Alt. Phone Number +65-90301090 Email Address automim.ops@gmail.com Address BLK 103A EDGEFIELD PLAINS #15-89 Address complement Postcode 821103 Is the driver the policyholder? Yes If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Chain Collision Weather Conditions Clear Road Surface Drv OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 3 Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) 2 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No PASSENGER 1 Name KAREN ANG Gender Female DETAILS OF POLICE ACTION

Was the accident reported to the police?

Was notice of intended Prosecution given?

No
If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

ON 16.09.2021 AT ABOUT 14.45 HOURS ALONG PIE TOWARDS CHANGI (BEFORE LORNIE ROAD EXIT 20B), I WAS TRAVELLING STRAIGHT ON LANE 2 AT THE ABOVE MENTIONED LOCATION AND WHEN THE FRONT VEHICLE (C) SLQ8822K SLOWED DOWN ANS STOPEED, HENCE I FOLLOWED SUIT.

SUDDENLY, I HEARD A LOUD BANG FROM BEHIND AND THE GREAT IMPACT FORCED MY VEHICLE (A) SLN8751Y TO MOVE FORWARD AND HIT ONTO THE REAR PORTION OF VEHICLE (C) SLQ8822K. WHEN I ALIGHTED, I REALISED IT WAS VEHICLE (B) GBF3041G THAT COLLIDED ONTO THE REAR PORTION OF MY VEHICLE (A) SLN8751Y, THUS CAUSING DAMAGES TO THE FRONT AND REAR PORTION OF MY VEHICLE (A) SLN8751Y.

IT WAS A CHAIN COLLISION OF TOTAL 3 VEHICLES INVOLVED
I WISH TO STATE THAT I HAVE ONE PASSENGER IN MY VEHICLE (A) SLN8751Y

ATTACHMENT(S)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

Was there any audio recorded?

No

(Draft)

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF3041G
Vehicle Manufacturer	_
Vehicle Model	7//
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	-
Name of Driver	•
Contact Number	-
Address complement	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Nature Of Damage	-
Details of property damaged in accident	_
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLQ8822K
Vehicle Manufacturer	CLGOOZZIN
Vehicle Model	-
Vohiolo Vorient	-
Vohiala Calaura	-
Vohiala Catanana	-
Vehicle Category	-
Name of Driver	-
Contact Number	-
Address	
Address complement	7
Postcode	-
Incurance Company Name	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	_

(RED \$17597.

= \$26797.10

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any will ulmisrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association
 of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the todgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)
- I understand, acknowledge, agree and consent that
- Tunderstand, occrrowledge, egree and consent too, .

 (a) My insurer, my workshop and the General haurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the haurors' lawyers/faw firms, the Monetary Authority of Singapore and any relevant novernment apencylauthority (such as the police). For the remeable of the remeable of the processing of the remeable of government agency/authority (such as the police), for the purpose(s) of ;
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims:
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (w) administering my claims (including the maling of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/faw firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (C) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

