

|   |        |      |             |
|---|--------|------|-------------|
| 1 | of 2 ? | 100% | Find   Next |
|---|--------|------|-------------|



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                                              |                          |            |  |
|----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------|--------------------------|------------|--|
| NTUC INCOME INSURANCE CO-OPERATIVE LTD                                                                                                 |                                                                                                              | Ref: CS/INC21009816/Bvf3 |            |  |
| 73 BRAS BASAH ROAD                                                                                                                     |                                                                                                              | Date: 21/09/2021         |            |  |
| #05-01 NTUC TRADE UNION HOUSESINGAPORE                                                                                                 |                                                                                                              |                          |            |  |
| 189556                                                                                                                                 |                                                                                                              | Code: INC                |            |  |
| 1. Policy Particulars :- THIRD PARTY CLAIM                                                                                             |                                                                                                              |                          |            |  |
| Insured Veh.                                                                                                                           | SFM 277D                                                                                                     | Veh. Inspected           | SLQ 2810J  |  |
| Policy No.                                                                                                                             |                                                                                                              | Coverage (\$)            | 0.00       |  |
| Claim No.                                                                                                                              | MT/1145097-002                                                                                               | Excess (\$)              | 0.00       |  |
| Assign From                                                                                                                            | ANNIE KOH                                                                                                    | Assign Date              | 21/09/2021 |  |
| 2. Vehicle Particulars & Condition                                                                                                     |                                                                                                              |                          |            |  |
| Make & Model                                                                                                                           | c.c                                                                                                          |                          | 0          |  |
| Engine No.                                                                                                                             | HIDDEN                                                                                                       | Year of Reg.             |            |  |
| Chassis No.                                                                                                                            |                                                                                                              | Colour                   |            |  |
| Odometer                                                                                                                               | -                                                                                                            | Steering                 |            |  |
| Brakes                                                                                                                                 |                                                                                                              | Modification             |            |  |
| General                                                                                                                                |                                                                                                              |                          |            |  |
| 3. Conditions of Tyres                                                                                                                 |                                                                                                              |                          |            |  |
|                                                                                                                                        | Size                                                                                                         | Make                     | Balance    |  |
| R/H Front Tyre                                                                                                                         |                                                                                                              |                          | mm         |  |
| L/H Front Tyre                                                                                                                         |                                                                                                              |                          | mm         |  |
| R/H Rear Tyre                                                                                                                          |                                                                                                              |                          | mm         |  |
| L/H Rear Tyre                                                                                                                          |                                                                                                              |                          | mm         |  |
| 4. Description of Damages                                                                                                              |                                                                                                              |                          |            |  |
|                                                                                                                                        |                                                                                                              |                          |            |  |
| 5. General Information                                                                                                                 |                                                                                                              |                          |            |  |
| Accident Date                                                                                                                          | 17/09/2021                                                                                                   | Inspection Date          | 21/09/2021 |  |
| Survey held at                                                                                                                         | REVOLUTION AUTOMOTIVE PTE LTD<br>8 KAKI BUKIT AVE 4, #01-49/50/51/52/53/54<br>PREMIER @ KB, SINGAPORE 415875 |                          |            |  |
| 5a. Remarks                                                                                                                            |                                                                                                              |                          |            |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                              |                          |            |  |