

Your Ref: CCL/nbmy/34184.1538

Date: 25<sup>th</sup> Oct 2021

Our Ref: CS1/LAW21009837/Avce2

**M/s Dentons Rodyk & Davidson LLP**

80 Raffles Place

#33-00, UOB Plaza

Singapore 048624

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: BJN 8800****INSURED VEHICLE: YM 4716C****ACCIDENT DATE: 19/10/2015**

We thank you for your instruction on 21/09/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of BJN 8800 from M/s Carlink Consultancy.
- b) Survey report by Appraisal VP Pte Ltd with colour photographs.
- c) Singapore Accident Statement of Vehicles YM 4716C.
- d) Police Report of Vehicles BJN 8800 and YM 4716C.
- e) Colour damaged vehicle photographs of BJN 8800.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

## 1. Information Recorded: -

Registration Number	: BJN 8800
Make & Model	: Scania R124 (RB/EPB ACH)
Chassis Number	: XLER6X20004466028
Year of Registration	: 2007

- 2. We recommend that the repairs of the entire damage require about 9 (Nine) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.