# ASS. REC. BY: TG Lim REF: C5/C7121809859/BVC

Veron

From: Date: 23/9/2021 Veh No: 5L   3810L Yr F	Regn: 26/16/2017
Estimated Cost: Type: A.Carl M.Cycle / Bus / Van / Lorry / Tax	xi / Prime Mover /
OD WS / TP RES / OD RES / EVA / INV / MV Truck / Trailer or	
To Inspect Vehicle No: SLT 3810L Make: Audi 6, 2	c.c 999
at Workshop m/s Bifrost Auto Colour Yellow A/C:	Insured / Std / NI / NA
of 8 Kaki Bot Ave 4 Premier #01-49 Sp. Reading 67030 T/Rai	dio: Insured / Std / NI / NA
Insured: Eng/No:	
Policy No. C/No: WAUZZZGA4HA	9 060 138 VEPA02619
Claims No. Gen. Cond: Good / Fair Poor / Burnt	
Sum Insured: Excess: Steering: Lorder / Jammed / Leaked / Burnt	or ·
(Client's Record) Brake: Inorder / Jammed / Leaked / Burnt	or
Make of Veh: Modi: Nil SRim / STD A/Rim or	
Tyre Size: F: 215/60/16	5
(Policy Condition) R: 215/60/16	
Remark: The veh had commenced its N/S O/S DUN / EXNOVA / GY / FS / LIZA / MIC / C	DHTSU/PIR/SUMI/
repair at the time of Inspection. TOYO / YOKO or	
Bal. or Market Value: 79.60 8	ĸ.
IDAC Accident Rport: Consistent? : Yes or No R/Bal. 4 mm , R/B	al. 4 mm
GIA / PR Seen: Consistent? : Yes or No UBal. 4 mm UB	al. 4 mm
Est. Repairs: 18 days Res.: Yes or No D.O.A. 18/9/2021 D.C.	23/9/2021
Lum Sum: % 3 Val.: Yes or No Survey held at Bifvost Au	110
CA / REV / REP. / 24 HRSWP	U/C / Rooftop or
Vehicle: IN / OUT	W. A. A. A. W. W. J.
Date: Person Contacted: The U/C / Chassis frame / Body Struc	ture affected due to collision.
Date / Time   Action / Instruction	
Range 24,000/ 25,000/2	
Rocommended COR IS LS \$ 24,350.00 Tolin h	in 10/1/2022
Macammenaea COR 1863 2 - 1,500 VI	
MY 79,000/2	
PV 39,219/2	Totim
NV 39,781/2	Mu 24/9/20
Date/Time, File Pass to? : Proli. Report Days Of Repair:	
The second secon	urvey Fee:
i)	ansportation:
502 (M. 1) 2 M. 1	_S + RSSI
: Interview (\$	Photos
	Officers
Format: : Tech. Invs (\$	
Lump Sum/I.E.t. (\$ ) : Westend (\$ )	

## BIFROST AUTO PTE LTD 8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAORE 415875

Tel: +65 64524457 Fax: +65 64524584

Company Reg No: 201929175W

Vehicle number: Make and model: Chassis: SLT3810L AUDI Q2 VEDA02619

Qty	Spare parts	List price >017	
1	Bonnet	S 22 05 60 2,789.00 DD	V
1	Bonnet RH hinge	S \( \langle 61.10 \cdot p 7	1
1	Bonnet LH hinge	\$ \( \sqrt{61.10} \)	0
1	Bonnet lock	\$ 57.70 JM	W
1	Bonnet RH lock cable	\$ \square 57.50 \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
1	Bonnet LH lock cable	\$ \( \sqrt{73.30} \)	
1	Bonnet insulator	S 219.00 NDX	<
1	Bonnet RH rubber seal	\$ \( \sqrt{29.50} \)	
1	Bonnet centre rubber seal	\$ \sqrt{34.50}\NE	9
1	Bonnet LH rubber seal	\$ \sqrt{29.50}	
1	Bonnet absorber stay	\$ 213.50 ND	V
1	Bonnet absorber stay bracket	\$ 34.80 N.D	
1	Front grille	\$ 1077.95 1,411.00 BR	
1	Front grille chrome moulding	S / 196.50 BK	-
1	Front grille lower garnish mesh	\$ \( \square 298.50 \)	
1	Front number plate holder	\$ 46.56 78.40 BR	/
1	Front bumper lower spoiler	\$ 249.00 298.50 MIS	51
1	Front bumper lower cover	\$ 51.00 155.80 BR	V
1	Front RH bumper	\$  893.50 BR	
1	Front RH bumper retainer	\$ ✓ 35.40 NE	CV
1	Front RH bumper air grille	\$ 108.00 169.00 BRL	1
1	Front RH bumper air grille inner cover	\$ √ 58.40 NEC	-
1	Front RH bumper parking sensor	\$ 150.00 285.00 52 V	
1	Front centre cover	\$ \147.50 BR	
1	Front LH bumper	\$ ∨ 893.50 BR	
1	Front LH bumper towing cover	\$ 38.60 NSX	7
1	Front LH bumper retainer	\$ √35.40 N €0	CV
1	Front LH bumper air grille	\$ 108,00 169.00 BR	1
1	Front LH bumper air grille inner cover	S √58.40 N €	W
1	Front LH bumper parking sensor	\$ 150.00 285.00 50	/
1	Front bumper reinforcement	\$ 578.40 723.00 DD	V
1	Front bumper inner sponge	\$ 77.40 NSX	(
1	RH headlamp	\$ 3,320.00 4,915.00 BR	W
1	RH headlamp bracket	\$ 43.4 118.00 BR	V
1	RH headlamp washer cover	S 57.20 NDX	4
1	RH headlamp washer nozzle	S √142.00 BR	11
1	LH headlamp	\$ 3,320.00 4,915.00 BR	1

	TITLE			
1	LH headlamp bracket	5	43:00	118.00 BRV
1	LH headlamp washer cover	5		57.20 NDX
1	LH headlamp washer nozzle	5		✓142.00 BRV
1	Radiator assy (no:1)	S		
1	Radiator assy (no:2)	5	1.12 00	879.50
1	Radiator fan assy	5		1,265.00 BK
1	Aircon condenser	5	.122100	
1	Support panel	5	ELLI MELLINE	994.00 BTU
1	Front RH fender			1,147.00 DDV
1	Front RH fender splash shield	5	m 1 1 000	195.00 ND
1	Front RH fender arch moulding	5		321.50 BRV
1	Front LH fender			1,147.00 NDX
1	Front LH fender splash shield	S		1,14,100 NDN
1	Front LH fender arch moulding	S		195.00 NDX
1	Washer tank	S	- 0	321.50 BR
î	Washer tank motor	S		176.00 NDX
î	Front RH low tone horn	S		124.50
1		S	100.00	186.00 350
1	Front RH high tone horn	\$	100.00	186.00
	-5%	s s s		29,379.70 1,468.99 27,910.72
<u>Qty</u>	Spare parts			
1	Front number plate	s	30.00	70.00 MISU
1set	Bonnet insulator clips	S	20.00	80.00 N NX
1set	Front bumper clips	S	30.00	70.00 NEC
1	Radiator coolant		Towns to the	120.00 NECV
1	Front number plate	S	40.00	70.00 RPX
1set	Front LH fender arch moulding dips	S	2000	
	Front RH fender arch moulding		30.00	60.00 NECV
	Tronc retrieve area mounding	3	30.00	-60.00 NEW
Labou	r and painting			
	r charges to remove, check, replace and reinstall damages bodyparts. nel beating, cut / weld and re-align all affected panels	s	800.00	1,800.00
Spray	painting on affected panels	s	800.00	1,500.00
Check	wiring and lighting system	S	5000	150.00
	rust coating chemical on affected panels	S		100.00 NNX
	vehicle on chassis alignment bench to straighten and repair both hassis members	\$		600.00

Remove and reprefill aircon gas	lace aircon condenser, pipes and hoses to assist repair. To	\$	220.00° NNX
Remove and rep To refill coolant	lace radiators assy, hoses, pipes and fan assy to assist repair.	\$ 120100	-280:00
Remove and rei	nstall engine with gearbox assy to assist repair	\$	-500:00 NNX
Reset and diagn	ose electronic control unit after repairs	\$ 250.00	320.00
Survey 22/9/2021	Resurvey 27/9/2021	\$ 3	33,910.72

# LKK Auto Consultants hence notify the Repairer of the following: To resurvey before/after spray painting To display damaged part(s) during resurvey

- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

BIFROST AUTO PTE LTD 8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAORE 415875 Tel: +65 64524457

Fax: +65 64524584

Qty Parts

Engine oil sump gasket sealant

Company Reg No: 201929175W

NOTE: REVISED OF PART PRICE

		Vehicle No: Model and make:		SLT3810L Audi Q2
Qty	Parts			List price
1	Engine oil sump		S	√1,353.00 BR ~
1	Engine oil sump gasket		5	63.80 137.00 NECV
1	Front crossmember		5	√ 1,378.00 BTV
1	Front RH lower arm		S	414.00 ) RPT
1	Front RH shock absorber		S	455.80 BT V
1	Front RH knuckle arm		S	-708.00 DDV
1	Front RH wheel bearing		S	530.00 + 1MV
1	Front RH lower arm		S	414.00 7 NDX
1	Front RH shock absorber		S	455.80 RPT
1	Front RH knuckle arm		\$	708.00 RPT
1	Front RH wheel bearing		\$	530.00/RPT
1	Steering rack and pinion		\$	4,546.00 NDX
1	Front RH drive shaft		S	2,211.00 } NDY
1	Front LH drive shaft		\$	2,085.00
1	Tunnel centre enforcement		S	V 203.00 BRV
1	Fuel tank		5	1.852.00 NDX
1	Rear axle beam		S	1694-06 2,741.00 BTV
1.	Rear RH shock asborber		S	305.00
1	Rear LH shock asborber		S	305.00 \ NDX
1	Rear RH wheel bearing		S	566.00
1	Rear LH wheel bearing		S	566.00
1	Exhaust silencer		S	1254 00 +,459.00 DDV
1	Exhaust silencer heat shield		S	✓ 251.00 DIS V
1	Exhaust centre pipe		S	V1,673.00 DDV
1	Exhaust centre pipe heat shield		S	225.00 355.00 DIS
			S	26,201.60
		-5%	S	1,310.08
			S	24,891.52

Special nett price

Engine oil	\$	80.00	180.00 NEC
Engine oil filter	\$		55.00 DD U
Brake fluid	S		7 <del>0.00</del> N 11 X
Labour			
Remove and replace engine oil sump and check for leakage	\$	80:00	280.00
Remove and replace front undercarriage parts	\$	300.00	550.00
Remove and replace fuel tank, pipes and sensor to assist repair	\$	60.00	120.00
Remove and replace rear undercarriage parts	\$	280-00	480.00
Remove and replace exhaust silencer and heat shield to assist repair	\$	80:00	200.00
Kesurve iz	s	2	6,976.52
16 45 Lv3			
Total hu			
	Parts	2736	2.86
	SN	29	5.00
Lump sem repair			
	Labour  Remove and replace engine oil sump and check for leakage  Remove and replace front undercarriage parts  Remove and replace fuel tank, pipes and sensor to assist repair  Remove and replace rear undercarriage parts  Remove and replace exhaust silencer and heat shield to assist repair  Resource y  5/10/2021  16.45 M3	Engine oil filter Brake fluid  Labour  Remove and replace engine oil sump and check for leakage  Remove and replace front undercarriage parts  Remove and replace fuel tank, pipes and sensor to assist repair  Remove and replace rear undercarriage parts  \$ Remove and replace exhaust silencer and heat shield to assist repair  \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	Engine oil filter Brake fluid  Labour  Remove and replace engine oil sump and check for leakage  Remove and replace front undercarriage parts  Remove and replace fuel tank, pipes and sensor to assist repair  Remove and replace rear undercarriage parts  Remove and replace exhaust silencer and heat shield to assist repair  Solver  Remove and replace exhaust silencer and heat shield to assist repair  Solver  Solve

LS 24350/2

LKK Auto Consultants hence notify the Repairer of the following:

Repair days 18

- To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

5litr

Talin Min 10/1/2022

30,477.86

24382.29

@20% 6095 57

Date of Accident	: 18/09/21 Accident Time: 10194/3 (24-HR-FORMAT)
Accident Place	: PARIR RIS DRIVE 10 /outside bix 7004
Vehicle Reg. No (Car plate No.)	: SL73810L Vehicle Make/Model: AUDI Q2
Insurance Company	: NIUL INLOWE Policy No. 5123386966
Name of Registered Owner	: Company / Individual OH DENG KINT BENJAMIN
ID of Registered Owner	: Co Reg No: Owner's NRIC No: \$ 822 51097
	: Co Contact No: Owner's Contact No: 9862417
DRIVER'S Name	: OH PENG KMT, SENJAMINDRIVER'S NRIC No: 582251092
DRIVER'S Date of Birth	06/08/1982 DRIVER'S License Pass Date 23/09/ 2002.
Relationship bet. Owner & Driver	: Spouse \ Parents \Children\ Sibling \ Employee\ Others:
DRIVER'S Address	BLK 752 PASIR RIS ST 71 408-88 5510752.
DRIVER'S Contact No./ Alt No.	:1) 4862479 2)
DRIVER'S Occupation	NDOOR \OUTDOOR (eg. working inside or outside of an ofc)
Email Address	BENJAMINOGOS @ GMAIL: COM
Weather & Road Surface	ELEAR & DRY \ RAINING & WET \AFTER RAIN & WET
Reporting Type	: Reporting Only Claim Other Party)\ Claim Own Insurance
Number of Passengers (including Days the accident reported to the pol Was there any video Captured by ca Exact purpose for which vehicle was Any injuries, if yes(name of the in	river): 2 Name & Gender; Mad ASH EVAN 64
	Party Driver's Particulars (if any)
Vehicle Reg No: SJE 7227H	Vehicle Reg No:
Vehicle Make Model: HONDA / FREE	
Name DRIVER:	
IC No. DRIVER:	
DRIVER'S Contact & add:	

#### SKEI UN FLAN

### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

lunderstand, acknowledge, agree and consent that :

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Abolder's Signature / Date &

Driver's Signature (If driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnel

Sketch Plan

ALONG PASIERS DE 10

vehicleA-SLIB3BIOT Vehicle B-SJL7227 A

Describe Circumstant	/	1	
Keter	16	police	report.
*	EA TO		
This is been as he had			
TO SHE VILLE			The state of the s
	William 1	C ADDITION	
	-		
			Total and the second se
The House and Associated I			
Tree or Production	T. W.		
	1 19.		
	-		

#### Declaration

We declare the foregoing particulars are true in every respect.





Police Station Of Origin:

Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

General Information of the Accident

Tel No: 65470000

1 of 3 Report No. T/20210918/7022

#### REPORT OF A TRAFFIC ACCIDENT

	ne Report ( )21 17:26	Made:	Vide Report No.: G/20210918/0141	Station Diary No.:	
Informa	nt's Partic	ulars			
	f Informant: IG KIAT, BI		Address: 752 PASIR RIS STREET 71:	#08-88 SINGAPORE 510752	
	/ ID No.: D / S82251	09Z	Contact No.: Home/Office:	Mobile: 98624179	
National SINGAP	ity: ORE CITIZ	EN	Email: BENJAMIN0608@GMAIL.COM		
Sex: Male	Age: 39	Date of Birth: 06/08/1982	Type of Informant: Driver	1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-	
Race: Chinese			Language: English	Institution / School Name:	
Occupation: Learning and Development Manager		opment Manager	Driving Licence Information: Class: 3	Date of Expiry:	

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 18/09/2021 10:15	Type of Location: Straight Road
Location: PASIR RIS DR	RIVE 10			
Weather: Clear		Road Surface:		Road Speed Limit:
Traffic Flow: One Way	1169	Traffic Control: Traffic Light - Wo	rking	Traffic Volume: Moderate
Type of Collisi Between Movi	on: ng Vehicles - Head To Side	e		Anyone conveyed by ambulance: No

Vehicle No.	Туре	Make	Model	Color	Conditio	No of
SJC7227H	Car	HONDA	Freed	White	Slightly Damaged	4
SLT3810L	Car	AUDI	Q2 1.0 TFSI	Yellow		2



T/20210918/7022

Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 2 of 3 Report No. T/20210918/7022

#### CONTINUATION OF REPORT

Details of V	ehicle Insurance			4,000,000,000,000,000,000
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLT3810L	NTUC Income Insurance Co-Operative Limited	5123386966	26/08/2021	25/08/2022

		218 222.00				THESE REAL PROPERTY.
Details of Perso	STATE OF THE PARTY					
Any Pedestrian		1,097				The state of the s
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA			
Passenger	Leading and Laurence			e anich de	e street	
Name	MONASH EVAN OH			ID No.		T1120601D
Related Vehicle	SLT3810L (Car)			Contact No.		
Hospital/Clinic	24 HOUR WALK-IN CLINIC		Class of Driving Licence & Expiry		Class: ,3 Date of Expiry: NIL	
Date	18/09/2021 Date		Date	18/09/2021		
No. of Days gran	ted Medical Leave	03	Degree of	f	Slight	
Driver						
Name	OH PENG KIAT, BENJAMIN			ID No.		S8225109Z
Related Vehicle	SLT3810L (Car)			Contact No.		98624179
Hospital/Clinic	24 HOUR WALK-IN CLINIC			Class of Driving Licence & Expiry		Class: 3 Date of Expiry: NIL
Date	18/09/2021		Date	18/09		/2021
No. of Days grant	o. of Days granted Medical Leave 04		Degree of		Slight	

#### Brief Details.

I was sending my son for his swimming lesson while approaching Block 700A car park exit. Out of a sudden, a vehicle came out from the stop line without checking for oncoming traffic. I realized that when I tried to e-brake and horn, it was to no avail. I ended up colliding head on with the vehicle and mounted the central divider.

After the accident, we went to consult a doctor at Intermedical Kovan. My son and I were both given medical certificate. I was given 4 days and my son was given 3 days MC.



Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000



3 of 3 Report No. T/20210918/7022

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch

Signature Of Officer Recording The Report: Not applicable

Signature Of Interpreter: Not applicable

Officer In Charge Of Case:
TP / TPHQ /
MOHAMED SUFIAN BIN MOHAMED JUNID
Contact No : 65475247

Signature Of Informant:

The identity of the person making this report has been authenticated by Singpass. No signature is required.

Date/Time:

18/09/2021 17:26

Classification Of Case:

## > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Singapore NRIC	1
Owner ID: Vehicle Details	109Z	
Vehicle No.:	SLT3810L	
Vehicle to be Exported:	No	
Intended Deregistration Date:	24 Sep 2021	
Vehicle Make:	AUDI /	
Vehicle Model:	Q2 1.0 TFSI STRONIC	
Primary Colour:	Yellow	
Manufacturing Year:	2017	
Engine No.:	CHZ390331	
Chassis No.:	VEDA02619	
Maximum Power Output:	85.0 kW (113 bhp)	
Open Market Value:	\$26,087.00	
Original Registration Date:	26 Oct 2017	
First Registration Date:	26 Oct 2017	
Transfer Count:	1	
Actual ARF Paid: Intended PARF Rebate Details	\$18,522.00	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	25 Oct 2027	
PARF Rebate Amount: Intended COE Rebate Details	\$13,891.00	
COE Expiry Date:	25 Oct 2027	
COE Category:	A - Car up to 1600cc & 97kW (130bhp)	
COE Period(Years):	10	
QP Paid:	\$41,617.00	
COE Rebate Amount:	\$25,328.00	
Total Rebate Amount:	\$39,219.00	

The Information contained herein is correct as at 24 Sep 2021

OK

MV 79,000/2 PV 39,219/2 NV 39,781/2

24/9/2021

#### SGCARMART.COM

Login Sign up

**New Cars** 

Used Cars

**Rental Cars** 

Sell My Car

Directory

2016 Mercedes-Benz A-Class A180 Style @ 73,8k

Products

Articles

Forum Resources



## BIDDED CARPLATE NUMBERS FOR SALE

Find and buy your favourite car plate number here!

START SEARCH NOW

Post an Advertisement Sell it yourself! Advertise it at lust

\$68 until it's SOLD!



Promol Interest Rate @ 1,88% Trust Motoring StarAd

YONG LEE SENG MOTOR PTE LTD





Posted: 28-Aug-2021 Tags: 2017 Audi Q2, Audi Q2, Audi, Q2



Audi A4 2.0T Quattro (For Lease)

\$2,399/mth Rare Audi A4 Upgraded with RS4 Kit, LTA approved Quad Exhaust, Tuned up to 265bhp and more! One & only available! More info about this vehicle



Audi Q2 1.0A TFSI S-tronic

\$79,988 \$12,000 /yr 17-Aug-2017

999 cc

80.000 km

SIIV

Available

5 Years / Unlimited Mileage Warranty By Agent Audi Singapore Till August 2022! 1 Owner. \$0 Downpayment / Low Interest Rate / Flexible Loan Schemes With High Approval Ratel High Trade-In For Your Used Vehicle. Buy With A Peace Of Mind, STA Evaluation U...

Posted: 22-Sep-2021 Tags: 2017 Audi Q2, Audi Q2, Audi, Q2



Audi Q2 1.0A TFSI S-tronic

\$83,800

\$12,640 /yr

16-Aug-2017

50.000 km

SHV

Available

PREMIUN AD

1 Owner, Low Usage, And Very Pristine Condition Grey Color Unit Like New, 5 Years Unlimited Warranty By Agent, One Of The Lowest Depreciation Unit In The Market. Although With A Low CC Engine, It Is Still Quite A Powerful And Smooth Drive. Test Drive.

Posted: 18-Sep-2021 Tags: 2017 Audi Q2, Audi Q2, Audi, Q2



Audi Q2 1.0A TFSI S-tronic

16-Aug-2017

999 cc

SUV

SOLD

1 Owner! Low Genuine Mileagel 5 Years Warranty Till Aug 2022! Fun And Easy Handling Compact SUV! Fuel-Efficiency, Fully Serviced By Agent! Trade-In Welcomed, Flexible Loan, Strictly View By Appointment Only! Don't Miss It, Call Now!

Posted: 25-Jul-2021 Tags: 2017 Audi Q2, Audi Q2, Audi, 02