



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL
(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924

Ref: CS/AGI21009857/Avf3n2

Date: 18/03/2022

Code: AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLE 4186C	Veh. Inspected	SLQ 2618Z
Policy No.		Coverage (\$)	0.00
Claim No.	C10011787/HA	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	21/09/2021

2. Vehicle Particulars & Condition

Make & Model	CHEVROLET ORLANDO	c.c	1362
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KL1YA7589HK616857	Colour	BROWN
Odometer	61513 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	MICHELIN	6 mm
L/H Front Tyre	215/60 R16	MICHELIN	6 mm
R/H Rear Tyre	215/60 R16	MICHELIN	6 mm
L/H Rear Tyre	215/60 R16	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/09/2021	Inspection Date	21/09/2021
Survey held at	XIN HUA WORKSHOP PTE LTD 23 KAKI BUKIT AVENUE 4 #04-01 (SOUTH WING) SINGAPORE 415933		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**