


ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 QD ☒ TP ☒ / N/S / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s AP AUTO
 of _____
 Insured: _____
 Policy No: _____
 Claims No: 638046
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: \$35k
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 7 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJZ2597B Yr Regn: 10 Nov 2010
 Type ☒ M.Car ☐ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: TOYOTA CAMRY 2.0 c.c. 1998
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 123878 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MR053BK4107061484 *
 Gen. Cond ☒ Good ☐ Fair / Poor / Burnt
 Steering: ☒ Inorder ☐ Jammed / Leaked / Burnt or
 Brake: ☒ Inorder ☐ Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / ☒ STD A/Rim or
 Tyre Size: F: 215/60R16
 R: 215/60R16
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / ☒ OKO or _____
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 22-09-2021
 Survey held at _____ W/S 4:30PM
 Des. of Damages ☒ Frt ☒ Rea ☐ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Total Rebate Amount \$16,535

30/09/21@5.36pm revised to Katherine Wong via Merimen. (Pending for parts prices)

01/03/22@10.50am email Christina Wong seek mandate at LS \$9550, 7 days.

07/03/22@10.13am Christina email: Hi Shiau Chan Please offer \$6800.00 and 7 working days.

08/03/22@12.48pm Zaleha informed that they accept MSIG offer at LS \$6800, 7 days.
 (Red \$29607.25, 81%)

Date/Time, File Pass to?

1) 08/03 Typist

Date/Time, File Return to?

2)

Report Filed at

Long Run 6800

MER-TP

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee:

☐ Site Insp (\$☐ Interview (\$☐ Tech. Insp (\$☐ W/Weekend (\$

Survey Fee:

Transportation:

\$ + RS. SI

Photos

Other:

TOTAL