

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE I	PTE LTD		Ref:	CC4/ASM21009860/Ugs3q2	
	8 SHENTON WAY AXA TOWERSING			Date:	15/12/2021	
	ATTN:CHAN KIAN	CHUAN		Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SH 9196S	Veh. Inspected	i	SLX 2083D	
	Policy No.	P2419138	Coverage (\$)		0.00	
	Claim No.	S1M03IAY	Excess (\$)		0.00	
	Assign From		Assign Date		21/09/2021	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA VIOS OPC (A)	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	MR2B23F3001115061	Colour		BLACK	
	Odometer	65909 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	185/60 R15	MICHELIN		7 mm	
	L/H Front Tyre	185/60 R15	MICHELIN		7 mm	
	R/H Rear Tyre	185/60 R15	MICHELIN		7 mm	
	L/H Rear Tyre	185/60 R15	MICHELIN		7 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	18/09/2021	Inspection Dat	e	21/09/2021	
	Survey held at	FASTECH AUTO PTE LTD				
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883				
5a.	. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:		4 Worki	ng Days	
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				