

ASS. REQ. BY:

Star

CS3/ASM 21009863/ETC

## ASSIGNMENT

From:

Date:

Estimated Cost:

OR / TP / WS / PERS / LOC / RES / EVAL / INV / LMV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Gillan's Record)

Make of Veh:

(Policy Condition)

Remarks: The veh had commenced its  
repairs at the time of inspection.

Rel. or Market Value:

155k

IDAC Accident Report

Consistent? : Yes or No

SIA / PR Sent

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Cum Sum:

%

3 Val.: Yes or No

QA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SDT 2682R

Yr Regn:

1

Types: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 530i

C.B.

1998

Colour:

Black

Sp. Reading

104579

A/O: Insured / Std / NI / N

T/Radio: Insured / Std / NI / N

Eng/No:

Ch/No:

W RATA 52080 G 886441

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brakes: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

275/35R19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Pirelli

Front

Rear

R/Bal:

4

mm

R/Bal:

4

mm

L/Bal:

4

mm

L/Bal:

4

mm

D.O.A.

18/9/21

D.O.A.

21/9/21

Survey held at

Trinice Automobile

Des. of Damages: FR / Rear / O/S / N/S / VIC / Rooftop or

The V/O / chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

No G/A report

repair large TK - 8K

6 repair days

SUBMIT PRS REPORT

Date/Time, File, Passed

☐

: Prel. Report

☐

: Final Report

Date/Time, File Return to

Days Of Repair:

6

Resurvey No. of Trips

Survey Fee:

Transportation

Add Fee:

☐

: Site Insp

(\$

☐

: Interview

(\$

☐

: Tech. Insp

(\$

☐

: VV&amp;I

(\$

S + RS

Photos

Quota

TOTAL

Date/Time, File Return to

Date/Time, File Return to