

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |  |  |                 |                         |  |
|---|--|--|-----------------|-------------------------|--|
|   | CHINA TAIPING IN   | ISURANCE (S) PTE LTD                                     | Ref:            | CS3/CTI21007935/Vqcn2-1 |  |
|   | 3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERSINGAPORE 079909  |  | Date:           | 30/09/2021              |  |
|   |  |  | Code:           | СТІ                     |  |
| 1.  | Policy Particulars :- THIRD PARTY CLAIM  |  |                 |                         |  |
|   | Insured Veh.   | SMS 5946J  | Veh. Inspected  | SMX 5026M               |  |
|   | Policy No.   | DMPCSNW00088012000                                       | Coverage (\$)   | 0.00                    |  |
|   | Claim No.  | SNM21D204051/C02   | Excess (\$)     | 0.00                    |  |
|   | Assign From  | JACQUELINE TAN   | Assign Date     | 21/09/2021              |  |
| 2.  | Vehicle Particulars & Condition  |  |                 |                         |  |
|   | Make & Model   | MERCEDES-BENZ C180                                       | c.c             | 1796                    |  |
|   | Engine No.   | HIDDEN   | Year of Reg.    | 2012                    |  |
|   | Chassis No.  | WDD2043492F839340  | Colour          | BLACK                   |  |
|   | Odometer   | 125346 KM  | Steering        | IN ORDER                |  |
|   | Brakes   | IN ORDER   | Modification    | STANDARD ALLOY RIM      |  |
|   | General  | GOOD   |                 |                         |  |
| 3.  | 3. Conditions of Tyres   |  |                 |                         |  |
|   |  | Size   | Make            | Balance                 |  |
|   | R/H Front Tyre   | 225/45 R17   | CONTINENTAL     | 5 mm                    |  |
|   | L/H Front Tyre   | 225/45 R17   | CONTINENTAL     | 5 mm                    |  |
|   | R/H Rear Tyre  | 225/45 R17   | CONTINENTAL     | 5 mm                    |  |
|   | L/H Rear Tyre  | 225/45 R17   | CONTINENTAL     | 5 mm                    |  |
| 4.  | Description of Damages   |  |                 |                         |  |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.   |  |                 |                         |  |
|   | DAMAGES SEE DETAILS.   |  |                 |                         |  |
| 5.  | General Information  |  |                 |                         |  |
|   | Accident Date  | 21/07/2021   | Inspection Date | 26/07/2021              |  |
|   | Survey held at   | A-TEC AUTOMOTIVE PTE LTD                                 | •               |                         |  |
|   |  | 8 KAKI BUKIT AVE 4<br>#05-27 PREMIER<br>SINGAPORE 415875 |                 |                         |  |
| 5a.   | Remarks  |  |                 |                         |  |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                 |                         |  |
| 5b.   | Estimate Days of Repair  |  |                 |                         |  |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days   |  |                 |                         |  |
|   | , ,  |  |                 |                         |  |