

REC BY: Thuan


CS3/CTI2007935/Vac -1

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 QD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: **SNM21D204051/C02**
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: ~~103k~~ **103k**
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: **34** days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SMX5026M** Yr Regn: **23/2/2012**
 Type: **M/Car** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: **Mercedes benz** c180 c.c. ~~599~~ **1796**
 Colour: **black** A/C: _____ Insured / Std / NI / NA
 Sp. Reading: **125346** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **WDD7043492F-839** ~~340~~
 Gen. Cond: **Good** / Fair / Poor / Burnt
 Steering: **In order** / Jammed / Leaked / Burnt or _____
 Brake: **In order** / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / **STD A/Rim** or _____
 Tyre Size: F: **225/45R17**
 R: **225/45R17**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Continental**

Front		Rear	
R/Bal.	5 mm	R/Bal.	5 mm
L/Bal.	5 mm	L/Bal.	5 mm
D.O.A.	21/7/21	D.O.I.	26/7/21 1700

 Survey held at **A-tee w/S**
 Des. of Damages: Frt / Rear / O/S / **N/S** / UIC / Roof/tp or _____
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MV: 103k
	Rebate: 62582
	NJ: 40418
	rr: 4k-5k
28/07/21	Submit PRS.
28/09/21	Submit LS \$3200, 4 days (Red \$11000, 77%)

Date/Time, File Pass to? ☐ : Preli. Report
28/09
 Typist ☐ : Final Report
 Date/Time, File Return to?

Days Of Repair: **34**

Resurvey No. of Trlp: **1**

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Wash and

Survey Fee:
 Transportation: _____
 S + RS: _____
 Fines: _____
 Other: _____
 Total: _____

Report Form: **-TP**
MER-PRO
3200