

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/1988 GS1 Reg. No. 19-900/198-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	F	Ref:	CS/AGI21009873/Kvf3n2	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	С	Date:	13/10/2021	
			C	Code:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SKK 2347Z	Veh. Inspected		SGK 3380S	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10011791/CD	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		21/09/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	HONDA CIVIC (A)	c.c		1799	
	Engine No.	HIDDEN	Year of Reg.		2006	
	Chassis No.	JHMFD16306S211290	Colour		METALLIC GOLD	
	Odometer	124802 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	205/55 R16	MICHELIN		6 mm	
	L/H Front Tyre	205/55 R16	MICHELIN		6 mm	
	R/H Rear Tyre	205/55 R16	MICHELIN		3 mm	
	L/H Rear Tyre	205/55 R16	MICHELIN		3 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	20/09/2021	Inspection Date		22/09/2021	
	Survey held at	POON SIANG SEOW				
		No.160 SIN MING DRIVE #05-13 SIN MING AUTOCITY SINGAPORE 575722				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: