



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 18/10/2021

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SG6173H
Case Reference Number	BUS/09/21/1006
Registration Date	20/3/2020
Company Type	SMRT Buses Ltd
Make	MAN
Model	A95 MAN E6
Name of Driver	Hao Lei
Type of Accident	Open Door Case
Accident Date and Time	14/9/2021 8:40 AM
Accident Reported Date and Time	17/9/2021 2:52 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24112362
Special Instruction to ARC,if any	SG6173H-LEFT FRONT PORTION AND FRONT LEFT BUMPER DENTED AND CRACKED SLX2476D (TP) INSURED WITH CHINA TAIPING
Prepared Date and Time	20/9/2021 1:59 PM
Chassis Number	WMAA95ZZXKF009722
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$530.00
Total Spray Cost	\$602.00	\$432.00
Total Spare Part Cost	\$300.00	\$300.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,697.00	\$1,262.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	2.0
Prepared / Adjusted By	Jeong Choon Hwee	Rasul
ARC / Surveyor Sign Off Date	20/09/2021 2:07 PM	21/09/2021 3:59 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 18/10/2021

User ID : CatherineLee

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope				Quotation from AR				Adjusted by Surveyor, if applicable	
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.				\$795.00				\$530.00	
Total Labour				\$795.00				\$530.00	
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope				Quotation from ARC				Adjusted by Surveyor, if applicable	
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS				\$602.00				\$432.00	
Total Spray Painting & Panel Beating				\$602.00				\$432.00	
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope				Quotation from ARC				Adjusted by Surveyor, if applicable	
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6013917			TRIM,WHEELARCH:FOR MAN A95 EURO 6	1.00	\$250.00	10.00	\$225.00	Replace	Replace
			SMRT STICKER	1.00	\$75.00	0.00	\$75.00	Replace	Replace
Total					\$325.00		\$300.00		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

✓ CRA
✓ NEC